

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/28/2026

Submitted Date:

02/09/2026

Document Number:

701104478

**FIELD INSPECTION FORM**

Loc ID 324025 Inspector Name: LONGWORTH, MIKE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10844  
Name of Operator: QB ENERGY OPERATING LLC  
Address: 1001 17TH STREET SUITE 1600  
City: DENVER State: CO Zip: 80202

**Findings:**

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Energy, QB		ecmc.inspections@qb-energy.com	<a href="#">QB Inspection mail box</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211522	WELL	PR	08/01/2023	GW	045-07282	BENTLEY 11-24	EG

**General Comment:**

[Flowline Integrity Inspection and Tank Integrity Inspection](#)  
Tank has rusted out holes and pinholes at top seam, tank top, and around valve.  
Comply with Rules 608.a.(10) Tank Venting Standards and 608.e Mechanical Conditions.  
CA Date 02/25/2026

**Location**

**Lease Road:**

	Type Access		
comment:			
Corrective ActionL			Date:

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:	Tank has rusted out holes and pinholes at top seem, tank top, and around valve.				
Corrective Action:	Comply with Rules 608.a.(10)Tank Venting Standards and 608.e Mechanical Conditions.				Date: 02/25/2026

**Paint**

Condition	Inadequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal				
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 211522 Type: WELL API Number: 045-07282 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404539123	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7444184">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7444184</a>
701104479	Flowline integrity inspection 701104478 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7444181">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7444181</a>