

TEP ROCKY MOUNTAIN LLC Clough RWF 22-14 Location # 335853



**TEP ROCKY MOUNTAIN LLC
Clough RWF 22-14
Location # 335853**



Damage to tank battery liner.

**TEP ROCKY MOUNTAIN LLC
Clough RWF 22-14
Location # 335853**



1" unused riser missing OOSLAT tag



2" unused poly pipe no OOSLAT

**TEP ROCKY MOUNTAIN LLC
Clough RWF 22-14
Location # 335853**



Unused equipment next to separator.