





**GP-25 CO<sub>2</sub> Well Location Photos**  
**API 05-083-06685**  
**Location ID 419721**  
**FIRR #404546038**



**Photo #1.** View of the GP-25 well location signage.




**Photo #2.** Close up view of the GP-25 flowline relief valve piping, where water was observed leaking. The drip leak on the relief valve piping was terminated.



**Photo #3.** View of the GP-25 flowline and relief valve piping, with impacted soils removed.



**Photo #4.** View of the GP-25 flowline and relief valve piping, with impacted soils removed.



**Figure #1.** Labeling of the components of the GP-25 flowline assembly.