

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/28/2026

Submitted Date:

02/10/2026

Document Number:

701104483

FIELD INSPECTION FORM

Loc ID 334733 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10844
Name of Operator: QB ENERGY OPERATING LLC
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Energy, QB		ecmc.inspections@qb-energy.com	QB Inspection mail box

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290042	WELL	SI	11/01/2023	GW	045-13962	MAP LLC 11-13 (PK11)	EG
290043	WELL	PR	05/01/2025	GW	045-13961	MAP LLC 11-14 (PK11)	EG
292399	WELL	PR	05/01/2025	GW	045-14721	MAP LLC 11-11BB (PK11)	EG
292400	WELL	PR	05/01/2025	GW	045-14720	MAP LLC 11-13BB (PK11)	EG
292488	WELL	SI	11/01/2023	GW	045-14729	MAP LLC 11-12BB (PK11)	EG

General Comment:

Flowline Integrity Inspection and Tank Integrity Inspection
Tank paint is peeling and fadding. Rust developing in strached areas and under label(s). Also man hatches around bolted seals. Monitor, inspect, and repair rust and paint for integrity.
Tank label is damaged with tank rusted behind it.
Install sign to comply with Rule 605.h.
CA Date 03/13/2026

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Tank label is damaged with tank rusted behind it.		
Corrective Action:	Install sign to comply with Rule 605.h.		Date: 03/13/2026

Emergency Contact Number:

Comment:			
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:			corrective date
Type:	#		
Comment:			
Corrective Action:			Date:

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,
Comment:	Tank paint is peeling and fadding. Rust developing in strached areas and under label (s). Also man hatches around bolted seals. Monitor, inspect, and repair rust and paint for integrity.				
Corrective Action:					Date:

Paint

Condition	Inadequate		
Other (Content)			
Other (Capacity)			

Other (Type) _____				
Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date: _____
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date: _____
Flaring:				
Type				
Comment:				
Corrective Action:				Date: _____

Inspected Facilities

Facility ID: 290042 Type: WELL API Number: 045-13962 Status: SI Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 290043 Type: WELL API Number: 045-13961 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 292399 Type: WELL API Number: 045-14721 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 292400 Type: WELL API Number: 045-14720 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 292488 Type: WELL API Number: 045-14729 Status: SI Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404540012	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7444941
701104484	Flowline integrity inspection 701104483 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7444937