

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/16/2026

Submitted Date:

02/17/2026

Document Number:

717300757

FIELD INSPECTION FORM

Loc ID 489372 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		ECMCInspections@Oxy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
247790	WELL	PA		GW	123-15588	DAVIS P27-3	PA
489373	TANK BATTERY	AC	02/24/2025		-	Davis P 27-3, 6,3JI ,6JI TB 489373	EG

General Comment:

[ECMC Engineering Integrity Inspection; Flowline Inspection](#)
[Photos uploaded](#)

Inspected Facilities

Facility ID: 247790 Type: WELL API Number: 123-15588 Status: PA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 489373 Type: TANK API Number: - Status: AC Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Well is plugged and abandoned (Davis 27-3); ECMC form 42 notice of start of plugging operations received Dec 2023. Wellhead OLF been removed. The facility/ tank battery has been decommissioned; tanks and equipment removed. ECMC form 42 notice of flowline abandonment completed April 2024 (OL facility FL's removed). No flowlines/ risers observed at PA well or facility/ battery areas. Remediation work is in progress.	maclarej	02/17/2026
As outlined on ECMC form 19 spill report Doc #404540115 received on 02/12/2026: While conducting flowline removal activities at the former Davis P 27-3 wellhead, historically impacted soil was discovered at the flowline at FL-B08@4'. The volume of the release is unknown. Assessment activities are ongoing. The flowline has been removed.	maclarej	02/17/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717300760	Fenced excavations at facility; No FL's/ risers	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7452734
717300761	View N to 27-3 PA well from facility/ battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7452735