

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/10/2026

Submitted Date:

02/17/2026

Document Number:

719500900

FIELD INSPECTION FORM

Loc ID 335978 Inspector Name: Morris, Matthew On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10844
Name of Operator: QB ENERGY OPERATING LLC
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

Findings:

- 12 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Energy, QB		ecmc.inspections@qb-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
299283	WELL	PR	05/19/2010	GW	045-17639	N. PARACHUTE EF09C-21 D27A 5	PR
299284	WELL	PR	05/28/2010	GW	045-17640	N. Parachute EF01D-28 D27A 5	PR
299285	WELL	PR	04/21/2010	GW	045-17641	N. PARACHUTE EF12D-22 D27A 5	PR
299286	WELL	PR	03/23/2010	GW	045-17642	N. PARACHUTE EF13B-22 D27A 5	PR
299287	WELL	PR	05/22/2010	GW	045-17643	N. PARACHUTE EF09A-21 D27A 5	PR
299288	WELL	PR	10/27/2008	GW	045-17644	N. PARACHUTE EF11C-22 D27A 5	PR
299289	WELL	PR	03/07/2010	GW	045-17645	N. PARACHUTE EF11A-22 D27A 5	PR
299290	WELL	PR	03/28/2010	GW	045-17646	N. PARACHUTE EF06A-22 D27A 5	PR
299291	WELL	PR	04/19/2010	GW	045-17647	N. PARACHUTE EF05C-22 D27A 5	PR
299292	WELL	PR	04/29/2010	GW	045-17648	N. PARACHUTE EF05A-22 D27A 5	PR
299293	WELL	PR	03/08/2010	GW	045-17649	N. PARACHUTE EF14A-22 D27A 5	PR
299294	WELL	PR	03/21/2010	GW	045-17650	N. PARACHUTE EF06C-22 D27A 5	PR
299295	WELL	PR	05/10/2010	GW	045-17651	N. PARACHUTE EF09D-21 D27A 5	PR
299299	WELL	PR	03/31/2010	GW	045-17652	N. PARACHUTE EF13C-22 D27A 5	PR

299386	WELL	PR	04/18/2010	GW	045-17662	N. PARACHUTE EF12A-22 D27A 5	PR
413296	WELL	PR	03/31/2010	GW	045-18771	N. PARACHUTE EF04A-27 D27A 5	PR

General Comment:

This is a field audit of the location, scout card, and related documents.

On 2/10/2026 at approximately 16:05, Compliance Inspector Matthew Morris conducted an on-site audit at QB ENERGY OPERATING LLC, N. PARACHUTE-65S95W/27NWNW at Location ID #335978 in Garfield County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

Location

Overall Good:

Signs/Marker:

Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	One sign is posted for all wells on location. Stamped steel tags hung on the wells are missing required information (API number) and are not conspicuously posted.		
Corrective Action:	Comply with CECMC Signage Requirements.	Date:	03/18/2026
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Good Housekeeping:

Type	DEBRIS		
Comment:	Trash/debris behind gas meters.		
Corrective Action:	Remove trash/debris.	Date:	02/25/2026

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	OTHER		
Comment:	Concrete barriers installed at gas meters/lift and ancillary equipment.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Concrete barriers		
Corrective Action:		Date:	

Equipment:

Type: Ancillary equipment	# 3		corrective date
Comment:	Chemical tanks		
Corrective Action:		Date:	

Type: Gas Meter Run	# 16		
Comment:	Open-ended hose at gas meters.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition.		Date: 02/25/2026
Type: Ancillary equipment	# 3		
Comment:	Line heaters		
Corrective Action:			Date:
Type: Bradenhead	# 16		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 16		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 16		
Comment:	Gas lift		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:	Tank paint is peeling, corrosion is present. No visible leaks.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	80 bbls
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal				
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
------	--

Comment:	
Corrective Action:	Date:

--

Inspected Facilities									
Facility ID:	299283	Type:	WELL	API Number:	045-17639	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	299284	Type:	WELL	API Number:	045-17640	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	299285	Type:	WELL	API Number:	045-17641	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	299286	Type:	WELL	API Number:	045-17642	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	299287	Type:	WELL	API Number:	045-17643	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	299288	Type:	WELL	API Number:	045-17644	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	299289	Type:	WELL	API Number:	045-17645	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	299290	Type:	WELL	API Number:	045-17646	Status:	PR	Insp. Status:	PR

Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 299291 Type: WELL API Number: 045-17647 Status: PR Insp. Status: PR

Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 299292 Type: WELL API Number: 045-17648 Status: PR Insp. Status: PR

Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 299293 Type: WELL API Number: 045-17649 Status: PR Insp. Status: PR

Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 299294 Type: WELL API Number: 045-17650 Status: PR Insp. Status: PR

Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 299295 Type: WELL API Number: 045-17651 Status: PR Insp. Status: PR

Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 299299 Type: WELL API Number: 045-17652 Status: PR Insp. Status: PR

Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 299386 Type: WELL API Number: 045-17662 Status: PR Insp. Status: PR

Producing Well			
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	413296	Type:	WELL	API Number:	045-18771	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
		Check Dams				
		Compaction				
				Material Handling And Spill Prevention		
Ditches						
		Gravel				
Berms						
		Culverts				
Gravel						
Compaction						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>During the audit, the following compliance issue(s) were observed:</p> <p>1) One sign is posted for all wells on location. Stamped steel tags hung on the wells are missing required information (API number) and are not conspicuously posted.</p> <p>2) Trash/debris on location</p> <p>3) Open-ended hose at gas meters</p> <p>A follow-up on this site audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p>	morrism	02/17/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719500901	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7453230