

Inspection Photos

Kinder Morgan YB-4

API # 05-083-06587

Inspector Name: James Blair. Inspection Date: 02/02/2026

Inspection Doc #: 721100131



1. Well sign with well in background.

Inspection Photos
Kinder Morgan YB-4
API # 05-083-06587

Inspector Name: James Blair. Inspection Date: 02/02/2026

Inspection Doc #: 721100131



2. Wellhead, well cellar, 1000 gallon diethylene glycol/produced water tank over secondary containment, 6" flowline with valve, annular vent behind barricaded, and solar pump. Contact information present.

Inspection Photos
Kinder Morgan YB-4
API # 05-083-06587

Inspector Name: James Blair. Inspection Date: 02/02/2026
Inspection Doc #: 721100131



3. Tank and flow line. Hazcom placard visible.

Inspection Photos
Kinder Morgan YB-4
API # 05-083-06587

Inspector Name: James Blair. Inspection Date: 02/02/2026
Inspection Doc #: 721100131



4. Well cellar, wellhead and bradenhead.

Inspection Photos
Kinder Morgan YB-4
API # 05-083-06587

Inspector Name: James Blair. Inspection Date: 02/02/2026
Inspection Doc #: 721100131



5. Well pad.

Inspection Photos
Kinder Morgan YB-4
API # 05-083-06587

Inspector Name: James Blair. Inspection Date: 02/02/2026
Inspection Doc #: 721100131



6. Well pad.

Inspection Photos
Kinder Morgan YB-4
API # 05-083-06587

Inspector Name: James Blair. Inspection Date: 02/02/2026
Inspection Doc #: 721100131



7. Well pad and reclamation vegetation.

Inspection Photos
Kinder Morgan YB-4
API # 05-083-06587

Inspector Name: James Blair. Inspection Date: 02/02/2026
Inspection Doc #: 721100131



8. Annular vent behind pipe barricade.

Inspection Photos
Kinder Morgan YB-4
API # 05-083-06587

Inspector Name: James Blair. Inspection Date: 02/02/2026
Inspection Doc #: 721100131



9. Access road.

Inspection Photos
Kinder Morgan YB-4
API # 05-083-06587

Inspector Name: James Blair. Inspection Date: 02/02/2026
Inspection Doc #: 721100131



10. Access road.