

Inspection Photos
Kinder Morgan HF-3
API # 05-083-06646

Inspector Name: James Blair. Inspection Date: 02/16/2026
Inspection Doc #: 721100152



1. Well sign near pad entrance gate.


Inspection Photos

Kinder Morgan HF-3

API # 05-083-06646

Inspector Name: James Blair. Inspection Date: 02/16/2026

Inspection Doc #: 721100152



Feb 16, 2026 at 4:32:37 PM

+37.483465,-108.885071

152° SE

Montezuma County

Energy & Carbon Management Commission

2. Wellhead and flow line riser. OOSLAT present.

Inspection Photos

Kinder Morgan HF-3

API # 05-083-06646

Inspector Name: James Blair. Inspection Date: 02/16/2026

Inspection Doc #: 721100152



3. Wellhead and flow line riser.

Inspection Photos

Kinder Morgan HF-3

API # 05-083-06646

Inspector Name: James Blair. Inspection Date: 02/16/2026

Inspection Doc #: 721100152



4. Wellhead. Bradenhead is accessible.

Inspection Photos
Kinder Morgan HF-3
API # 05-083-06646

Inspector Name: James Blair. Inspection Date: 02/16/2026
Inspection Doc #: 721100152



5. Wellhead and flow line riser. Well pad is clean and free of undesirable vegetation.

Inspection Photos
Kinder Morgan HF-3
API # 05-083-06646

Inspector Name: James Blair. Inspection Date: 02/16/2026
Inspection Doc #: 721100152



 **COLORADO**
Energy & Carbon Management
Commission
Department of Natural Resources

Feb 16, 2026 at 4:33:59 PM
+37.483797, -108.885174
49° NE

Montezuma County
Energy & Carbon Management Commission

6. Annular vent.

Inspection Photos

Kinder Morgan HF-3

API # 05-083-06646

Inspector Name: James Blair. Inspection Date: 02/16/2026

Inspection Doc #: 721100152



7. Access road. Note culvert on left side of road.

Inspection Photos

Kinder Morgan HF-3

API # 05-083-06646

Inspector Name: James Blair. Inspection Date: 02/16/2026

Inspection Doc #: 721100152



8. Interim vegetation and 4 strand barbed wire fence surrounding pad within location.