

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/12/2026

Submitted Date:

02/18/2026

Document Number:

721100131

**FIELD INSPECTION FORM**

Loc ID 313577 Inspector Name: Blair, Jamie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 46685  
Name of Operator: KINDER MORGAN CO2 CO LLC  
Address: 1001 LOUISIANA ST SUITE 1000  
City: HOUSTON State: TX Zip: 77002

**Findings:**

8 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
224522	WELL	PR	09/01/2023	CO2	083-06587	YB 4	PR

**General Comment:**

At 10:30 AM on Tuesday, February 12, 2026, southwest compliance specialist Jamie Blair conducted a compliance inspection and audit. No corrective actions were identified. Photos are included as an attachment.

**Location**

Overall Good:

Emergency Contact Number:

Comment: [Photo 1.](#)

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type OTHER

Comment: [Pipe barricades around annular vents.](#)

Corrective Action:

Date:

**Equipment:**

corrective date

Type: Bradenhead # 1

Comment:

Corrective Action:

Date:

Type: Flow Line # 1

Comment: [6" stainless with ball valve.](#)

Corrective Action:

Date:

Type: Other # 1

Comment: [1000 gallon skid-mounted tank mounted above secondary containment with expanded metal top. Laballed Diethylene glycol/produced water. Tank is 90% full. No fluid in secondary containment. Paint ok. Hazcom placard.](#)

Corrective Action:

Date:

Type: Ancillary equipment # 1

Comment: [Solar pump/telmetry on tank.](#)

Corrective Action:

Date:

Type: Deadman # & Marked # 0

Comment: [None observed.](#)

Corrective Action:

Date:

Type: Other # 1

Comment: [wellhead](#)

Corrective Action:

Date:

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 224522 Type: WELL API Number: 083-06587 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 07/17/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 3 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
721100141	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7453446">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7453446</a>