

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/18/2026

Submitted Date:

02/18/2026

Document Number:

716301977

**FIELD INSPECTION FORM**

Loc ID 333948 Inspector Name: Beardslee, Tom On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10705  
Name of Operator: EVERGREEN NATURAL RESOURCES LLC  
Address: 1775 SHERMAN ST. #2775  
City: DENVER State: CO Zip: 80203

**Findings:**

- 11 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Evergreen	719-846-7898	cogcc.evergreen@enrllc.com	<a href="#">All Inspections</a>
D DYKE, TRACY	719-846-7898	tracy.dyke@enrllc.com	<a href="#">Insp. w/ca's</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277923	WELL	PR	07/24/2005	CBM	071-08393	OINK OINK 14-36 TR	PR
277925	WELL	TA	05/25/2012	OBW	071-08394	OINK OINK 14-36	TA

**General Comment:**

"This is a field audit of the scout card, related documents and the location."

**Location**

Overall Good:

**Signs/Marker:**

	Type OTHER		
Comment:	PHOTO 2: ACCORDING TO ECMC RECORDS THE API # FOR THE OINK OINK 14-36 TR IS 05-071-08393 NOT 08383.		
Corrective Action:	POST SIGN PER RULE 605.	Date:	03/17/2026

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

						corrective date
Type: Deadman # & Marked	# 4					
Comment:						
Corrective Action:						Date:
Type: Vertical Separator	# 1					
Comment:						
Corrective Action:						Date:
Type: Ancillary equipment	# 1					
Comment:						
Corrective Action:						Date:
Type: Bradenhead	# 1					
Comment:	IS ACCESSABLE					
Corrective Action:						Date:
Type: Gas Meter Run	# 1					
Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.					
Corrective Action:						Date:
Type: Progressive Cavity	# 1					
Comment:						
Corrective Action:						Date:
Type: Prime Mover	# 1					
Comment:						
Corrective Action:						Date:

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 277923 Type: WELL API Number: 071-08393 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 11/10/2011 Annual Brhd Completed? \_\_\_\_\_

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: FORM 4 #2319084

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 277925 Type: WELL API Number: 071-08394 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: WELL HAS BEEN CONVERTED TO A SEISMIC MONITOR WELL FORM 4 #400701995

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 11/10/2011 Annual Brhd Completed? \_\_\_\_\_

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: FORM 4 #2319083

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Produced Water      Lined: NO      Pit ID: 281069      Lat: 37.208428      Long: -104.847537

Reference Point: \_\_\_\_\_      Other: \_\_\_\_\_      Length: \_\_\_\_\_      Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_      Liner Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: None      Fencing Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_      Netting Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

Anchor Trench Present: NO      Oil Accumulation: NO      2+ feet Freeboard: YES

Comment:

Corrective Action

Date: \_\_\_\_\_

Permit:	Facility ID	Permit Num	Expiration Date
	281070	1393344	
	281069	1393343	

**ECMC Comments**

Comment	User	Date
<p><a href="#">ECMC Inspection Report Summary</a>                      Date: 2/17/2026                      Time: 09:53                      Operator: EVERGREEN NATURAL RESOURCES LLC 10705                      Location: OINK OINK 14-36 TR                      API# 05-071-08393                      County: Las Animas County.                      While there, I ECMC staff performed a field audit of the scout card, related documents and the location. During the audit the following possible compliance issues were observed: API # INCORRECT FOR TR WELL, RULE 605, CA DUE DATE 3/17/2026                      A follow-up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p>	beardslt	02/18/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716301979	INSP. PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7453610">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7453610</a>