

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/10/2026

Submitted Date:

02/12/2026

Document Number:

721100118

FIELD INSPECTION FORM

Loc ID 419721 Inspector Name: Blair, Jamie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46685
Name of Operator: KINDER MORGAN CO2 CO LLC
Address: 1001 LOUISIANA ST SUITE 1000
City: HOUSTON State: TX Zip: 77002

Findings:

- 11 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Blair, Jamie		jamie.blair@state.co.us	
General		CO2Source_Regulatory@kindermorgan.com	All SW field inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
419722	WELL	SI	03/27/2012	CO2	083-06685	GOODMAN POINT (GP) 25	SI

General Comment:

Southwest compliance specialist James Blair performed a compliance inspection and audit on Tuesday, February 10, 2026. 2 corrective actions is observed: 1) produced water is dripping from a 2" pipe coming off the main flow line, 2) staining the gravel below. No other corrective actions were observed.

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Near pad entrance. See photo 1.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	24 hour 970-882-5522. Emergency 911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	Stained soil caused by drip beneath flow line. See photo 6.		
Corrective Action:	Clean up stained soil to comply with 612.a.(2). Submit form 19 if determined more than 1 bbl of E&P waste released.		Date: <u>03/13/2026</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No _____			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type			
Comment:	Cattle panel around flow line.		
Corrective Action:		Date:	
Equipment:			
			corrective date
Type: Bradenhead	# 1		
Comment:	Photo 5.		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	wellhead. Photo 4.		
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:	Produced water is dripping off a blow-down valve coming off the main flow line about 10 feet west of the wellhead. See photos 06 and 07.		
Corrective Action:	Mechanical Conditions: Ensure that all production facilities, valves, pipes, fittings, and vessels will be securely fastened or sealed, inspected at regular intervals, and maintained in good mechanical condition to comply with 608.e		Date: <u>02/16/2026</u>
Venting:			
Yes/No	NO		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 419722 Type: WELL API Number: 083-06685 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: 6/7/2023 MIT date.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 10/10/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Repair leak on flow line and clean up stained soil beneath. See Housekeeping, and Equipment: Flow Line for CAs.	blairj1	02/10/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404542962	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7447639
721100122	Photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7447633