

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/18/2026

Submitted Date:

02/19/2026

Document Number:

717300766

**FIELD INSPECTION FORM**

Loc ID 321469 Inspector Name: Maclaren, Joe On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10633  
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC  
Address: 555 17TH STREET SUITE 3700  
City: DENVER State: CO Zip: 80202

**Findings:**

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name       | Phone | Email                         | Comment |
|--------------------|-------|-------------------------------|---------|
|                    |       | Inspections@civiresources.com |         |
| Schlagenhauf, Mark |       | mark.schlagenhauf@state.co.us |         |

**Inspected Facilities:**

| Facility ID | Type     | Status | Status Date | Well Class | API Num   | Facility Name                           | Insp Status |
|-------------|----------|--------|-------------|------------|-----------|---|-------------|
| 282565      | WELL     | SI     | 10/01/2025  | GW         | 013-06524 | BAILEY 11-12                            | PA          |
| 336389      | LOCATION | AC     |             |            | -         | DONIPHAN SHIELDS NENE MULTI-WELL 8-4-11 | EG          |

**General Comment:**

ECMC Engineering Integrity Inspection; Flowline Inspection  
Photos uploaded

**Inspected Facilities**

Facility ID: 282565 Type: WELL API Number: 013-06524 Status: SI Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 336389 Type: LOCATION API Number: - Status: AC Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

| Comment   | User     | Date       |
|---|----------|------------|
| As outlined on ECMC form 19 spill report Doc #404544892 received on 02/13/2026: Historical impacts were discovered during decommission activities. Source removal will be scheduled.  | maclarej | 02/19/2026 |
| Wells is PA (Bailey 11-12); ECMC form 42 notice of start of plugging operations doc #404471013 received 12/12/2025. Facility decommissioning work is completed; flowline removal work (on location/ facility) is also completed. Wellhead OLF has been removed; bellhole excavations observed at flowline pipe removal pull points between WH & battery (backfilled). Remediation work (at PA well) is in progress. | maclarej | 02/19/2026 |

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                            | URL   |
|--------------|--|---|
| 717300767    | WH OLF removed; BH Exc view to battery | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7455757">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7455757</a> |
| 717300768    | Facility decommissioned                | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7455758">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7455758</a> |