

**Inspection Photos**  
**UPRR 50 Pan Am D-1**  
**Spill ID 482826/Remediation Project No 27721**



**Photo 1 – Open excavation; excavation has been partially backfilled**

**Photo 2 - Open excavation; excavation has been partially backfilled**

**Inspection Photos**  
**UPRR 50 Pan Am D-1**  
**Spill ID 482826/Remediation Project No 27721**



**Photo 3 - Open excavation; excavation has been partially backfilled**



**Photo 4 - Open excavation; excavation has been partially backfilled**

Inspection Photos  
UPRR 50 Pan Am D-1  
Spill ID 482826/Remediation Project No 27721



**Photo 5 – Cement in backfill in open excavation (red). Uncapped pipe (purple) and t-post (blue) present in open excavation.**



**Photo 6 – Cement used in backfill in open excavation.**

Inspection Photos  
UPRR 50 Pan Am D-1  
Spill ID 482826/Remediation Project No 27721



**Photo 7 - Uncapped pipe in open excavation.**

**Photo 8 - Uncapped pipe in open excavation.**

Inspection Photos  
UPRR 50 Pan Am D-1  
Spill ID 482826/Remediation Project No 27721



**Photo 9 - Cement in backfill in open excavation (red). Uncapped pipe (purple) and t-post (blue) present in open excavation.**

**Photo 10 – Soil stockpiles on location for backfill**

Inspection Photos  
UPRR 50 Pan Am D-1  
Spill ID 482826/Remediation Project No 27721



**Photo 11 - Soil stockpiles on location for backfill**



**Photo 12 - Soil stockpiles on location for backfill;  
trash present in backfill**

Inspection Photos  
UPRR 50 Pan Am D-1  
Spill ID 482826/Remediation Project No 27721



**Photo 13 - Soil stockpiles on location for backfill;  
concrete present in backfill**



**Photo 14 - Soil stockpiles on location for backfill;  
concrete present in backfill**

**Inspection Photos**  
**UPRR 50 Pan Am D-1**  
**Spill ID 482826/Remediation Project No 27721**



**Photo 15 - Soil stockpiles on location for backfill;  
concrete present in backfill**



**Photo 16 - Soil stockpiles on location for backfill;  
concrete present in backfill**

Inspection Photos  
UPRR 50 Pan Am D-1  
Spill ID 482826/Remediation Project No 27721



ECMC Environmental Inspection  
40.07345, -104.76591, 1520.1m, 253°  
02/18/2026 12:21:56 PM



ECMC Environmental Inspection  
40.07334, -104.76604, 1520.0m, 92°  
02/18/2026 12:25:05 PM

**Photo 17 – Area of previously stockpiled contaminated soil; a small amount of soil remains within the stockpile. “Contaminated” marker and liner still present. Holes in liner visible. Weeds throughout.**

**Photo 18 – Area of previously stockpiled contaminated soil; a small amount of soil remains within the stockpile. “Contaminated” marker and liner still present. Holes in liner visible. Weeds throughout.**

Inspection Photos  
UPRR 50 Pan Am D-1  
Spill ID 482826/Remediation Project No 27721



Photo 19 – Well sign



Photo 20 – UPRR 50 Pan Pam D#1 wellhead. Stained soil at wellhead and surrounding area.

**Inspection Photos**  
**UPRR 50 Pan Am D-1**  
**Spill ID 482826/Remediation Project No 27721**



**Photo 21 – Stained soil present near UPRR 50 Pan Pam D#1 wellhead.**

**Photo 22 - UPRR 50 Pan Pam D#1 wellhead. Stained soil at wellhead and surrounding area.**