

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/10/2026

Submitted Date:

02/13/2026

Document Number:

719500894

**FIELD INSPECTION FORM**

Loc ID 335824 Inspector Name: Morris, Matthew On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10844  
Name of Operator: QB ENERGY OPERATING LLC  
Address: 1001 17TH STREET SUITE 1600  
City: DENVER State: CO Zip: 80202

**Findings:**

- 9 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone | Email                          | Comment |
|--------------|-------|--------------------------------|---------|
| Energy, QB   |       | ecmc.inspections@qb-energy.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name               | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------------|-------------|
| 281919      | WELL | PR     | 04/03/2007  | GW         | 045-11570 | N.PARACHUTE EF08B C27A 595  | PR          |
| 281923      | WELL | PR     | 04/03/2007  | GW         | 045-11575 | N. PARACHUTE EF09D C27A 595 | PR          |
| 281924      | WELL | PR     | 04/03/2007  | GW         | 045-11576 | N.PARACHUTE EF 16B C27A 595 | PR          |
| 281930      | WELL | PR     | 04/03/2007  | GW         | 045-11577 | N.PARACHUTE EF06B C27A 595  | PR          |
| 281931      | WELL | PR     | 04/03/2007  | GW         | 045-11578 | N.PARACHUTE EF 10B C27A 595 | PR          |
| 281933      | WELL | PR     | 04/03/2007  | GW         | 045-11579 | N.PARACHUTE EF 16D C27A 595 | PR          |
| 281935      | WELL | PR     | 04/03/2007  | GW         | 045-11580 | N.PARACHUTE EF01B C27A 595  | PR          |
| 281936      | WELL | PR     | 04/03/2007  | GW         | 045-11581 | N.PARACHUTE EF07B C27A 595  | PR          |

**General Comment:**

This is a field audit of the location, scout card, and related documents.

On 2/10/2026 at approximately 15:45, Compliance Inspector Matthew Morris conducted an on-site audit at QB ENERGY OPERATING LLC, N.PARACHUTE-65S95W/27NENW at Location ID #335824 in Garfield County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

**Location**

Overall Good:

| <b>Signs/Marker:</b> |  |       |            |
|----------------------|--|-------|------------|
| Type                 | CONTAINERS   |       |            |
| Comment:             |  |       |            |
| Corrective Action:   |  | Date: |            |
| Type                 | BATTERY  |       |            |
| Comment:             |  |       |            |
| Corrective Action:   |  | Date: |            |
| Type                 | TANK LABELS/PLACARDS   |       |            |
| Comment:             |  |       |            |
| Corrective Action:   |  | Date: |            |
| Type                 | WELLHEAD   |       |            |
| Comment:             | One sign is posted for all wells on location. Stamped steel tags hung on the wells are missing required information (API number) and are not conspicuously posted. |       |            |
| Corrective Action:   | Comply with CECMC Signage Requirements.  | Date: | 03/24/2026 |

|                                  |                   |       |       |
|----------------------------------|-------------------|-------|-------|
| <b>Emergency Contact Number:</b> |                   |       |       |
| Comment:                         | 911/(970)285-2615 |       |       |
| Corrective Action:               |                   | Date: | _____ |

Overall Good:

| <b>Spills:</b> |      |        |  |
|----------------|------|--------|--|
| Type           | Area | Volume |  |
|                |      |        |  |

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

| <b>Fencing/:</b>   |   |       |  |
|--------------------|---|-------|--|
| Type               | WELLHEAD  |       |  |
| Comment:           | Concrete barriers   |       |  |
| Corrective Action: |   | Date: |  |
| Type               | OTHER   |       |  |
| Comment:           | Concrete barriers installed at gas meters/lift and ancillary equipment. |       |  |
| Corrective Action: |   | Date: |  |

| <b>Equipment:</b>         |     |       | corrective date |
|---------------------------|-----|-------|-----------------|
| Type: Bradenhead          | # 8 |       |                 |
| Comment:                  |     |       |                 |
| Corrective Action:        |     | Date: |                 |
| Type: Gas Meter Run       | # 8 |       |                 |
| Comment:                  |     |       |                 |
| Corrective Action:        |     | Date: |                 |
| Type: Ancillary equipment | # 2 |       |                 |

|   |     |       |
|---|-----|-------|
| Comment: <a href="#">Chemical tanks</a> |     | Date: |
| Corrective Action:                      |     | Date: |
| Type: Plunger Lift                      | # 8 |       |
| Comment:                                |     | Date: |
| Corrective Action:                      |     | Date: |
| Type: Ancillary equipment               | # 5 |       |
| Comment: <a href="#">Line heaters</a>   |     | Date: |
| Corrective Action:                      |     | Date: |
| Type: Gas Meter Run                     | # 8 |       |
| Comment: <a href="#">Gas lift</a>       |     | Date: |
| Corrective Action:                      |     | Date: |

**Tanks and Berms:**

| Contents           | # | Capacity  | Type      | Tank ID | SE GPS |
|--------------------|---|-----------|-----------|---------|--------|
| PRODUCED WATER     | 1 | <100 BBLs | STEEL AST |         |        |
| Comment:           |   |           |           |         |        |
| Corrective Action: |   | Date:     |           |         |        |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) | 80 bbls  |
| Other (Type)     |          |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              |          |                     |                     |             |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          | Date:               |                     |             |

**Venting:**

|                    |    |       |
|--------------------|----|-------|
| Yes/No             | NO | Date: |
| Comment:           |    | Date: |
| Corrective Action: |    | Date: |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  | Date: |
| Comment:           |  | Date: |
| Corrective Action: |  | Date: |

| Inspected Facilities   |        |       |      |             |           |         |    |               |    |
|--|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:   | 281919 | Type: | WELL | API Number: | 045-11570 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b>  |        |       |      |             |           |         |    |               |    |
| Comment:   |        |       |      |             |           |         |    |               |    |
| Corrective Action:   |        |       |      |             |           |         |    | Date:         |    |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12 |        |       |      |             |           |         |    |               |    |
| Facility ID:   | 281923 | Type: | WELL | API Number: | 045-11575 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b>  |        |       |      |             |           |         |    |               |    |
| Comment:   |        |       |      |             |           |         |    |               |    |
| Corrective Action:   |        |       |      |             |           |         |    | Date:         |    |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12 |        |       |      |             |           |         |    |               |    |
| Facility ID:   | 281924 | Type: | WELL | API Number: | 045-11576 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b>  |        |       |      |             |           |         |    |               |    |
| Comment:   |        |       |      |             |           |         |    |               |    |
| Corrective Action:   |        |       |      |             |           |         |    | Date:         |    |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12 |        |       |      |             |           |         |    |               |    |
| Facility ID:   | 281930 | Type: | WELL | API Number: | 045-11577 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b>  |        |       |      |             |           |         |    |               |    |
| Comment:   |        |       |      |             |           |         |    |               |    |
| Corrective Action:   |        |       |      |             |           |         |    | Date:         |    |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12 |        |       |      |             |           |         |    |               |    |
| Facility ID:   | 281931 | Type: | WELL | API Number: | 045-11578 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b>  |        |       |      |             |           |         |    |               |    |
| Comment:   |        |       |      |             |           |         |    |               |    |
| Corrective Action:   |        |       |      |             |           |         |    | Date:         |    |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12 |        |       |      |             |           |         |    |               |    |
| Facility ID:   | 281933 | Type: | WELL | API Number: | 045-11579 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b>  |        |       |      |             |           |         |    |               |    |
| Comment:   |        |       |      |             |           |         |    |               |    |
| Corrective Action:   |        |       |      |             |           |         |    | Date:         |    |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12 |        |       |      |             |           |         |    |               |    |
| Facility ID:   | 281935 | Type: | WELL | API Number: | 045-11580 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b>  |        |       |      |             |           |         |    |               |    |
| Comment:   |        |       |      |             |           |         |    |               |    |
| Corrective Action:   |        |       |      |             |           |         |    | Date:         |    |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12 |        |       |      |             |           |         |    |               |    |
| Facility ID:   | 281936 | Type: | WELL | API Number: | 045-11581 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b>  |        |       |      |             |           |         |    |               |    |
| Comment:   |        |       |      |             |           |         |    |               |    |
| Corrective Action:   |        |       |      |             |           |         |    | Date:         |    |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12 |        |       |      |             |           |         |    |               |    |

**Producing Well**

|                    |  |       |
|--------------------|--|-------|
| Comment:           |  |       |
| Corrective Action: |  | Date: |

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs                          | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| Berms            |                 |                         |                       |  |                          |         |
| Ditches          |                 |                         |                       |  |                          |         |
| Compaction       |                 |                         |                       |  |                          |         |
|                  |                 | Compaction              |                       |  |                          |         |
|                  |                 |                         |                       | Material Handling And Spill Prevention |                          |         |
|                  |                 | Culverts                |                       |  |                          |         |
|                  |                 | Gravel                  |                       |  |                          |         |
|                  |                 | Check Dams              |                       |  |                          |         |
| Gravel           |                 |                         |                       |  |                          |         |
|                  |                 | Ditches                 |                       |  |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

| Comment  | User    | Date       |
|--|---------|------------|
| <p>During the audit, the following compliance issue(s) were observed:</p> <p>1) One sign is posted for all wells on location. Stamped steel tags hung on the wells are missing required information (API number) and are not conspicuously posted.</p> <p>A follow-up on this site audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p> | morrism | 02/13/2026 |

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 404545684    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7450319">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7450319</a> |
| 719500895    | Photo Log            | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7450318">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7450318</a> |