

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404552514

Date Received:
02/20/2026

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10777
Name of Operator: RAMPIKE RESOURCES LTD
Address: 730 17TH STREET SUITE 999
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Coleman, Chris</u>		<u>chris.coleman@state.co.us</u>
<u>Costa, Ryan</u>		<u>ryan.costa@state.co.us</u>
<u>Sharp, Neil</u>	<u>(720) 464-7603</u>	<u>nsharp@rampikeresources.com</u>
<u>Waggoner, Kyle</u>		<u>kyle.waggoner@state.co.us</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 710500718
Inspection Date: 02/03/2026 FIR Submit Date: 02/06/2026 FIR Status: _____

Inspected Operator Information:

Company Name: RAMPIKE RESOURCES LTD Company Number: 10777
Address: 730 17TH STREET SUITE 999
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 324797

Location Name: DAWSON A-619S45W Number: 9NENW County: _____
Qtrqtr: NENW Sec: 9 Twp: 19S Range: 45W Meridian: 6
Latitude: 38.424012 Longitude: -102.466545

FACILITY - API Number: 05-061-00 Facility ID: 324797

Facility Name: DAWSON A-619S45W Number: 9NENW
Qtrqtr: NENW Sec: 9 Twp: 19S Range: 45W Meridian: 6
Latitude: 38.424012 Longitude: -102.466545

CORRECTIVE ACTIONS:

1 CA# 210850

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a. If the Impacts to soils meet any of the criteria listed in 912.b. Operator shall file an Initial Form 19-I and contact area EPS for directives

Date: 02/13/2026

Response: CA COMPLETED

Date of Completion: 02/13/2026

Operator Comment: Operator has securely fastened all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, and will continue to inspect at regular intervals to maintain all are in good mechanical condition per Rule 608.e. Stained soils around the wellhead have been properly cleaned up per Rule 912.a. Stained soils around the wellhead did not meet Rule 912.b; a Form 19I was not required. Location photos are attached.

ECMC Decision: _____

ECMC Representative: _____

2 CA# 210851

Corrective Action: Remove debris and Comply with Rule 606.

Date: 02/13/2026

Response: CA COMPLETED

Date of Completion: 02/13/2026

Operator Comment: Weed debris around within the machine guarding have been removed and disposed of per Rule 606. Location photos are attached.

ECMC Decision: _____

ECMC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Amber Barnett

Signed: _____

Title: Compliance Specialist

Date: 2/20/2026 11:30:58 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404552514	FIR RESOLUTION SUBMITTED
404552554	Location Photos

Total Attach: 2 Files