



PHOTO 1: THE AREA OF IMPACTED SOIL AROUND THE WELLHEAD HAS BEEN REMOVED AND REPLACED WITH FRESH PAD MATERIAL. THE SELF INSPECTION PROCESS HAS BEEN REVIEWED AND THIS LOCATION WITH BE MONITORED FOR ANY FURTHER POTENTIAL COMPLIANCE ISSUES.