

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/20/2026

Submitted Date:

02/20/2026

Document Number:

713302508

**FIELD INSPECTION FORM**

Loc ID 331279 Inspector Name: Kester, Michael On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 65110  
Name of Operator: O'BRIEN ENERGY RESOURCES CORP  
Address: 18 CONGRESS ST STE 207  
City: PORTSMOUTH State: NH Zip: 03801

**Findings:**

9 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Forma, Joseph	603-427-2099 x111	joeforma@obenergy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260833	WELL	TA	07/30/2020	GW	123-20424	LOST CREEK O'BRIEN 3-20	TA

**General Comment:**

[well site inspection](#)

**Location**

Overall Good:

**Signs/Marker:**

	Type WELLHEAD		
	Comment: <span style="color: blue;">good</span>		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 80%;" type="text"/>

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

	Type WELLHEAD		
	Comment: <span style="color: blue;">metal panels, bent badly</span>		
Corrective Action:		Date:	

**Equipment:**

				corrective date
Type: Bradenhead	# 1			
Comment:	<span style="color: blue;">piped to surface</span>			
Corrective Action:		Date:		
Type: Ancillary equipment	# 1			
Comment:	<span style="color: blue;">automation</span>			
Corrective Action:		Date:		
Type: Plunger Lift	# 1			
Comment:				
Corrective Action:		Date:		

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 260833 Type: WELL API Number: 123-20424 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: SITE CONDITION

Comment: Valves appeared to be closed at time of inspection

Corrective Action:  Date:

**BradenHead**

Date of Last Brhd Test: 10/21/2024 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: submit report

Corrective Action:  Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<p><a href="#">Audit of scout card and related documents</a>  <a href="#">Follow up inspection as per Doc # 717701644,</a>  <a href="#">corrective actions appeared to have been addressed</a>  <a href="#">Well was found in state of Temporary Abandonment,</a>  <a href="#">last mIT 10-23-2023</a></p> <p><a href="#">This inspection does not nullify any orders or NOAV from the ECMC</a></p>	kesterm	02/20/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713302509	site pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7457461">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7457461</a>