

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/02/2026

Submitted Date:

02/21/2026

Document Number:

713401247

FIELD INSPECTION FORM

Loc ID 314562 Inspector Name: Popejoy, Dusty On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10779
Name of Operator: SCOUT ENERGY MANAGEMENT LLC
Address: 13800 MONTFORT DRIVE SUITE 100
City: DALLAS State: TX Zip: 75240

Findings:

15 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Wiley, Mikel		Mikel.Wiley@scoutep.com	
Rosado, Sydney		Sydney.Rosado@scoutep.com	
Saint, John		jsaint@scoutep.com	
Sanford, Anita		anita.sanford@scoutep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229049	WELL	PR	08/01/2019	OW	103-06127	GRAY B 16	PR

General Comment:

[This is a Field Inspection/audit of the scout card, related documents and the location.](#)

Location

Lease Road:			
Type	Access		
comment:	Access		
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	OTHER		
Comment:	Sign at entrance to location		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Wellhead sign lacks public road used to access the well. No tank battery on location		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	970-675-3700/911		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:	Debris on location, refer to photos		
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Equipment:			corrective date
Type: Submersible Pump	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Bradenhead valve is accessible/equipped with gauge - BH line tied into flowline		
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 229049 Type: WELL API Number: 103-06127 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well equipped with ESP

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 08/19/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 180 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: BH line tied into flowline FORM 4 SUNDRY document #402687438

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				Light compaction
		Ditches				
Gravel						Sparse
Berms						
Compaction						Light compaction
		Gravel				Sparse

Comment: Operator is responsible for maintaining Best Management Practices (BMP's) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary</p> <p>On 02/2/2026 at approximately 15:15 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection/audit at SCOUT ENERGY MANAGEMENT LLC GRAY B #16 PAD at Location ID #314562 in Rio Blanco County, Colorado.</p> <p>This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority, NSO, Density Habitat regulations.</p> <p>While there, I observed normal production operations.</p> <p>This is a summary of inspection/audit report.</p>	popejoyd	02/21/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713401250	713401247 Inspection-Audit Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7457466