

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/16/2026

Submitted Date:

02/21/2026

Document Number:

708908516

FIELD INSPECTION FORM

Loc ID 334825 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

46 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
TEP		ECMCInspectionReports@flywheelenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210977	WELL	PR	09/05/1998	GW	045-06735	BATTLEMENT MESA PARTNERS GV 82-5	PR
211185	WELL	PR	12/21/1995	GW	045-06944	CURFMAN W 15-5	PR
293561	WELL	PR	07/27/2008	GW	045-15041	BATTLEMENT MESA PARTNERS PA 433-5	PR
293563	WELL	PR	11/19/2007	GW	045-15042	BATTLEMENT MESA PARTNERS PA 434-5	PR
293564	WELL	PR	03/01/2023	GW	045-15043	BATTLEMENT MESA PARTNERS PA 424-5	PR
293565	WELL	PR	03/01/2023	GW	045-15044	BATTLEMENT MESA PARTNERS PA 24-5	PR
301575	WELL	PR	02/28/2010	GW	045-18184	BATTLEMENT MESA PA 423-5	PR
301576	WELL	PR	12/18/2009	GW	045-18185	BATTLEMENT MESA PA 524-5	PR
301577	WELL	PR	01/31/2010	GW	045-18186	BATTLEMENT MESA PA 333-5	PR
301578	WELL	PR	02/17/2009	GW	045-18187	BATTLEMENT MESA PA 13-5	PR
301579	WELL	PR	09/01/2022	GW	045-18188	BATTLEMENT MESA PA 324-5	PR
301580	WELL	PR	04/16/2011	GW	045-18189	BATTLEMENT MESA PA 323-5	PR
301581	WELL	PR	04/16/2011	GW	045-18190	BATTLEMENT MESA PA 314-5	PR
301582	WELL	PR	04/16/2011	GW	045-18191	BATTLEMENT MESA PA 23-5	PR
301583	WELL	PR	04/16/2011	GW	045-18192	BATTLEMENT MESA PA 313-5	PR

301584	WELL	PR	01/31/2010	GW	045-18193	BATTLEMENT MESA PA 14-5	PR
301585	WELL	PR	02/28/2010	GW	045-18194	BATTLEMENT MESA PA 514-5	PR
301586	WELL	PR	04/16/2011	GW	045-18195	BATTLEMENT MESA PA 34-5	PR
301587	WELL	PR	04/16/2011	GW	045-18196	BATTLEMENT MESA PA 414-5	PR
301588	WELL	PR	01/31/2010	GW	045-18197	BATTLEMENT MESA PA 413-5	PR
301589	WELL	PR	04/16/2011	GW	045-18198	BATTLEMENT MESA PA 334-5	PR
301590	WELL	PR	04/16/2011	GW	045-18199	BATTLEMENT MESA PA 33-5	PR

General Comment:

[This is a Field Inspection/Audit of the scout card, related documents and the location.](#)

Location

Lease Road:			
	Type	Access	
	comment:		
	Corrective Action		Date:

Overall Good:

Signs/Marker:			
	Type	OTHER	
	Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.	
	Corrective Action:		Date:
	Type	WELLHEAD	
	Comment:		
	Corrective Action:		Date:
	Type	CONTAINERS	
	Comment:	Chemical tanks	
	Corrective Action:		Date:
	Type	BATTERY	
	Comment:		
	Corrective Action:		Date:
	Type	TANK LABELS/PLACARDS	
	Comment:		
	Corrective Action:		Date:

Emergency Contact Number:			
	Comment:	911/970-285-9377	
	Corrective Action:		Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No _____

Comment: _____

Multiple Spills and Releases?

Fencing/:			
	Type	TANK BATTERY	
	Comment:	Hog panels	
	Corrective Action:		Date:
	Type	SEPARATOR	
	Comment:	Hog panels	
	Corrective Action:		Date:

Type	OTHER		
Comment:	Chemical tanks & thermogen - hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 3		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 20		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 20		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 20		
Comment:	CURFMAN W 15-5 well not on plunger lift, remaining 21 wells all on plunger lift		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 6		
Comment:	Marked		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Thermogen		
Corrective Action:		Date:	
Type: Bradenhead	# 20		

Comment:	CURFMAN W 15-5 well has Taylor plug located on bradenhead, bradenhead valve is accessible.			
	Remaining 21 wells have pressure transducers & Taylor plugs located on bradenheads, bradenhead valves are accessible.			
Corrective Action:			Date:	
Type: Bird Protectors	# 12			
Comment:				
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:	Tank equipped with telemetry				
Corrective Action:				Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		
Comment:	Centralized containment			
Corrective Action:			Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLs	STEEL AST		,
Comment:	Tanks equipped with telemetry				
Corrective Action:				Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		
Comment:	Centralized containment			
Corrective Action:			Date:	

Venting:

Yes/No	NO	
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 210977 Type: WELL API Number: 045-06735 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 03/04/2025 Annual Brhd Completed? _____
 Last Brhd Test Results Initial Surf Csg Pressure: 35 Fluid Type: NONE
 End Surf Csg Pressure: 0
 Comment: BH line tied into separator - Form 4 SUNDRY document #'s 402298778 & 403338539
 Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 211185 Type: WELL API Number: 045-06944 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well not on plunger lift
 Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 293561 Type: WELL API Number: 045-15041 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift
 Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 293563 Type: WELL API Number: 045-15042 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift
 Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 293564 Type: WELL API Number: 045-15043 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift
 Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 293565 Type: WELL API Number: 045-15044 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift
 Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 301575 Type: WELL API Number: 045-18184 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 301576 Type: WELL API Number: 045-18185 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 301577 Type: WELL API Number: 045-18186 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 301578 Type: WELL API Number: 045-18187 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 301579 Type: WELL API Number: 045-18188 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 301580 Type: WELL API Number: 045-18189 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 301581 Type: WELL API Number: 045-18190 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 301582 Type: WELL API Number: 045-18191 Status: PR Insp. Status: PR

Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	301583	Type:	WELL	API Number:	045-18192	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	301584	Type:	WELL	API Number:	045-18193	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	301585	Type:	WELL	API Number:	045-18194	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	301586	Type:	WELL	API Number:	045-18195	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	301587	Type:	WELL	API Number:	045-18196	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	301588	Type:	WELL	API Number:	045-18197	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	301589	Type:	WELL	API Number:	045-18198	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well			
Comment:	Producing, well on plunger lift		

Corrective Action:		Date:	
--------------------	--	-------	--

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	301590	Type:	WELL	API Number:	045-18199	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				Sparse to none in most sections
Sediment Traps						
		Compaction				Light compaction in some sections
Compaction						Light compaction in areas
				Material Handling And Spill Prevention		Chemical tank containments
Rip Rap						
		Ditches				
Gravel						Sparse to none in areas
Ditches						
		Culverts				
Drains						
Berms						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary On 02/16/2026 at approximately 14:13 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection/audit at TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA PARTNERS GV 82-5 Pad. Location # 334825 in Garfield County Colorado. Location is within High Priority/Density/NSO/Black Bear Habitat areas & Bald Eagle Roost sites. Location is within Rule 411a Surface Water Internal Buffer & Rule 411b Generalized Internal Buffer. Location is approximately 39 yards from the Colorado River. While there, I observed normal production operations.</p> <p>This is a summary of inspection/audit report.</p>	smelserw	02/21/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708908517	Inspection/Audit 708908516 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7457471
708908518	Inspection/Audit 708908516 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7457472