

# Interim Reclamation and Stormwater Inspection

February 13, 2026

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 428867

Well Name: Rehder #X06-20D

Inspection Document #: 718601377

Weld County, CO

Anthony Dunnam  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Rehder #X06-20D  
Location ID: 428867



**Photo 1.** Looking east down the access road across the well area. Desirable perennial vegetation appears to be progressing in the interim area. Tumbleweed is present touching equipment.



**Photo 2.** Looking north across the eastern wells. Signs appear to have been damaged by wind.



Inspection Photos  
Location Name: Rehder #X06-20D  
Location ID: 428867



**Photo 3.** Looking east across the eastern portion of the well turnaround area. It appears some desirable vegetation is progressing in this area.



**Photo 4.** Looking west down the north side of the well area. Desirable perennial vegetation is present in the interim area.



Inspection Photos  
Location Name: Rehder #X06-20D  
Location ID: 428867



**Photo 5.** Photo taken at the wet side of the tank battery. Tumbleweed present.



**Photo 6.** Separators at the tank battery have tumbleweed in contact with equipment.



Inspection Photos  
Location Name: Rehder #X06-20D  
Location ID: 428867



**Photo 7.** Storage tanks on the east side of the tank battery.



**Photo 8.** Looking west across the south side of the tank battery interim area. Desirable perennial vegetation appears to be progressing in this area.



Inspection Photos  
Location Name: Rehder #X06-20D  
Location ID: 428867



**Photo 9.** Reference vegetation to the north of the well area. Reference vegetation is primarily undesirable weedy species.