

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/20/2026

Submitted Date:

02/23/2026

Document Number:

717300773

FIELD INSPECTION FORM

Loc ID 336527 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		ECMCInspections@Oxy.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
488002	TANK BATTERY	AC	09/25/2024		-	Russell15-25A&Tom L1 Facility TB	EG

General Comment:

ECMC Engineering Integrity Inspection; Flowline Inspection
Photos uploaded

Inspected FacilitiesFacility ID: 488002 Type: TANK API Number: - Status: AC Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
As outlined on ECMC form 19 spill report Doc #404549166 received on 02/13/2026: While conducting flowline removal activities at the former Russell Tom L C 1 wellhead, historically impacted soil was discovered at the wellhead. The volume of the release is unknown. Assessment activities are ongoing. The flowline has been removed.	maclarej	02/23/2026
Well is plugged and abandoned (Tom Russel 1); ECMC form 42 notice of start of plugging operations received April 2024. The facility/ tank battery has been decommissioned; tanks and equipment removed. ECMC form 42 notice of flowline abandonment completed January 2024. No flowlines/ risers observed at PA well or facility/ battery areas. Remediation work is in progress.	maclarej	02/23/2026

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717300777	Location; No open excavations	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7457897
717300778	Location; view south	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7457898