

# QB ENERGY OPERATING LLC FEDERAL HAGEN-67S95W 16NESE Facility # 335041



**QB ENERGY OPERATING LLC  
FEDERAL HAGEN-67S95W 16NESE  
Facility # 335041**



**Flaking rusted tank around bottom of tank man hatch.**



**Flaking rusted tank around bottom of tank man hatch.**

**QB ENERGY OPERATING LLC  
FEDERAL HAGEN-67S95W 16NESE  
Facility # 335041**



**Rusty bottom on the tank man hatches.**



**Rusty bottom on the tank man hatches.**

**QB ENERGY OPERATING LLC  
FEDERAL HAGEN-67S95W 16NESE  
Facility # 335041**



**Tank damage on top of tank at tank thief hatch.**



**Hole in tank seem from tank damage.**

**QB ENERGY OPERATING LLC  
FEDERAL HAGEN-67S95W 16NESE  
Facility # 335041**



**Rust corrosion in middle of tank top.**