

Inspection Photos

Location Name: LARAMIE ENERGY LLC CC 0629-02 Pad

Location ID: 335149



Photo # 1557 From entrance to location




Photo # 1558 Location

Inspection Photos
Location Name: LARAMIE ENERGY LLC CC 0629-02 Pad
Location ID: 335149



Photo # 1559 Location



Photo # 1560 Location

Inspection Photos

Location Name: LARAMIE ENERGY LLC CC 0629-02 Pad

Location ID: 335149



Photo # 1561 Location




Photo # 1562 Stored/unused equipment

Inspection Photos

Location Name: LARAMIE ENERGY LLC CC 0629-02 Pad

Location ID: 335149



**Photo # 1563 Open ended pipe on stored equipment
/wildlife hazard/available for entry by wildlife**



**Photo # 1564 Open ended pipes on stored equipment
/wildlife hazards/available for entry by wildlife**

Inspection Photos
Location Name: LARAMIE ENERGY LLC CC 0629-02 Pad
Location ID: 335149



Photo # 1565 Open hatch on stored equipment/wildlife hazard/available for entry by wildlife



Photo # 1566 Wildlife & safety protection around hole needs maintenance

Inspection Photos

Location Name: LARAMIE ENERGY LLC CC 0629-02 Pad

Location ID: 335149



Photo # 1567 Wildlife & safety protection around hole needs maintenance



Photo # 1568 Debris

Inspection Photos

Location Name: LARAMIE ENERGY LLC CC 0629-02 Pad

Location ID: 335149



Photo # 1569 Unused flowline lacks lockout tagout (OOSLAT)



Photo # 1570 Unused flowline lacks lockout tagout (OOSLAT)