

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/23/2026

Submitted Date:

02/23/2026

Document Number:

708908538

FIELD INSPECTION FORM

Loc ID 335149 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10433
Name of Operator: LARAMIE ENERGY LLC
Address: 1700 LINCOLN ST STE 3950
City: DENVER State: CO Zip: 80203

Findings:

- 22 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Longworth, Mike		mike.longworth@state.co.us	
Heil, John		john.heil@state.co.us	
LARAMIE ENERGY		cogccnotifications@laramie-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211110	WELL	PR	03/16/2015	GW	045-06869	CASCADE CREEK 629-2	PR
276976	WELL	PR	06/01/2023	GW	045-10566	CASCADE CREEK 697-29-10D	PR
276982	WELL	PR	06/17/2006	GW	045-10564	CASCADE CREEK 697-29-30D	PA
276984	WELL	PR	10/20/2014	GW	045-10563	CASCADE CREEK 697-29-38D	PR

General Comment:

[This is a Field Inspection/Audit of the scout card, related documents and the location.](#)

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Sign at start of spur road to location		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	911/1-800-891-6191		
Corrective Action:		Date:	
Good Housekeeping:			
Type	DEBRIS		
Comment:	Debris - please refer to photo log		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Wildlife & safety protection around hole needs maintenance		
Corrective Action:	Comply with CECMC Rule 602	Date:	02/25/2026
Type	UNUSED EQUIPMENT		
Comment:	Stored/unused equipment on location - rig tank Additionally there are multiple open ended pipes & an open hatch on the rig tank which all constitute wildlife hazards/not in compliance with CECMC rules		
Corrective Action:	Comply with CECMC Rule 606	Date:	03/25/2026
Overall Good: <input type="checkbox"/>			
Spills:			

Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				
Equipment:				corrective date
Type: Other		# 1		
Comment: Rig tank - unused/stored equipment please refer to Housekeeping for CA				
Corrective Action:				Date:
Type: Bradenhead		# 3		
Comment: CASCADE CREEK 697-29-10D well has no form of pressure monitoring equipment located on bradenhead, bradenhead valve is accessible. CASCADE CREEK 629-2 & CASCADE CREEK 697-29-38D wells have Taylor plugs located on bradenheads, bradenhead valves are accessible.				
Corrective Action:				Date:
Type: Plunger Lift		# 2		
Comment: CASCADE CREEK 629-2 well not on plunger lift CASCADE CREEK 697-29-10D & CASCADE CREEK 697-29-38D wells on plunger lift				
Corrective Action:				Date:
Type: Gas Meter Run		# 5		
Comment:				
Corrective Action:				Date:
Type: Dehydrator		# 3		
Comment:				
Corrective Action:				Date:
Type: Horizontal Heated Separator		# 5		
Comment:				
Corrective Action:				Date:
Type: Bird Protectors		# 6		
Comment:				
Corrective Action:				Date:
Type: Other		# 1		
Comment: Unused flowline lacks lockout tagout (OOSLAT)				
Corrective Action: Comply with CECMC Rule 1101				Date: 03/02/2026

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		
Comment: Tank equipped with telemetry					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	

Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 211110 Type: WELL API Number: 045-06869 Status: PR Insp. Status: PR

Producing Well

Comment:	Producing, well not on plunger lift	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 276976 Type: WELL API Number: 045-10566 Status: PR Insp. Status: PR

Producing Well

Comment:	Producing, well on plunger lift	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 276982 Type: WELL API Number: 045-10564 Status: PR Insp. Status: PA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: P & A
 FORM 6 document # 404262997
 FORM 6 Subsequent document # 404543127 "IN PROCESS"
 FORM 42 document #'s 404493384 & 404493387
 FORM 42 document #'s 404501016 & 404501015

Corrective Action:		Date:
--------------------	--	-------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 276984 Type: WELL API Number: 045-10563 Status: PR Insp. Status: PR

Producing Well

Comment:	Producing, well on plunger lift	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Sediment Traps				
Compaction						Light compaction in some areas
Waddles						
		Rip Rap				
Other	Fail					Soil stockpile lacks BMP's
		Gravel				Sparse to none
		Compaction				Light compaction in some sections
		Ditches				
Ditches						
		Culverts				

Comment: [1. Soil stockpile lacks BMP's](#)

Corrective Action: [Comply with CECMC Rule 1002](#)

Date: 03/10/2026

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary On 02/23/2026 at approximately 10:36 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection/audit at LARAMIE ENERGY LLC CC 0629-02 Pad Location # 335149 in Garfield County Colorado. Location is within High Priority/Density/NSO/Black Bear Habitat areas. Location is approximately 86 yards from Conn Creek. While there, I observed normal production operations.</p> <p>During this inspection/audit the following compliance issues were observed:</p> <ol style="list-style-type: none"> 1. Housekeeping - Stored/unused equipment on location - Comply with Rule 606 with a CA date of 03/25/2026 2. Housekeeping - Wildlife & safety protection around hole needs maintenance - Comply with Rule 602 with a CA date of 02/25/2026 3. Equipment - Unused flowline lacks lockout tagout (OOSLAT) - Comply with Rule 1101 with a CA date of 03/02/2026 4. Stormwater - Soil stockpile lacks BMP's - Comply with Rule 1002 with a CA date of 03/10/2026 <p>Comments -</p> <p>Housekeeping - Debris</p> <p>A follow up on this site inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules. This is a summary of inspection/audit report.</p> <p>Any corrective actions from previous inspections/audits that have not been addressed are still applicable.</p>	smelserw	02/23/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708908539	Inspection/Audit 708908538 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7458795
708908540	Inspection/Audit 708908538 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7458796