

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/06/2026

Submitted Date:

02/17/2026

Document Number:

701104499

**FIELD INSPECTION FORM**

Loc ID 323900 Inspector Name: LONGWORTH, MIKE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

- 5 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-285-9377	ECMCInspectionReports@flywheelenergy.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211127	WELL	PR	12/05/1994	GW	045-06886	CLOUGH RMV 7-21	EG

**General Comment:**

Flowline Integrity Inspection  
2" unknown riser with open valve and no plug. Riser is south of well near and yellow anchor marker.  
Comply with OOSLAT 1100 Series Rules. ASAP (24 hrs)  
Determine what the flowline is or was for and if needs abandoned. Contact ECMC Integrity Inspector Mike Longworth  
CA Date 02/27/2026  
A grounding rod near unused riser. A rusty old valve and some lumber near unused riser.  
Comply with Rule 606  
CA Date 03/06/2026

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	No API # on well sign.		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	911		
Corrective Action:		Date:	

**Good Housekeeping:**

Type	DEBRIS		
Comment:	A grounding rod near unused riser. A rusty old valve and some lumber near unused riser.		
Corrective Action:	Comply with Rule 606	Date:	03/06/2026

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type: Flow Line	# 1		corrective date
Comment:	2" unknown riser with open valve and no plug. Riser is south of well near and yellow anchor marker.		
Corrective Action:	Comply with OOSLAT 1100 Series Rules. ASAP (24 hrs) Determine what the flowline is or was for and if needs abandoned. Contact ECMC Integrity Inspector Mike Longworth.		Date: 02/27/2026

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 211127 Type: WELL API Number: 045-06886 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404547689	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7452394">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7452394</a>
701104500	Flowline integrity inspection 701104499 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7452393">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7452393</a>