

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/24/2026

Submitted Date:

02/24/2026

Document Number:

715801965

FIELD INSPECTION FORM

Loc ID 318309 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 13 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241089	WELL	SI	05/01/2021	OW	123-08877	SUCKLA-BROWN UNIT 16	SI

General Comment:

[This is a field audit of the scout card, related documents and the location. Follow up to FIR Doc# 715801388.](#)

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Good Housekeeping:

Type	WEEDS		
Comment:	tall vegetation throughout location & around the eqipment needs to be removed.		
Corrective Action:	Comply with rule 606	Date:	08/26/2025

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	wood & metat post with barb wire		
Corrective Action:		Date:	
Type	OTHER		
Comment:	fabricated steel pipe around the ancillary equipment		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	fabricated steel pipe		
Corrective Action:		Date:	

Equipment:

Type: Ancillary equipment	# 2		corrective date
Comment:	telemetry, electric panel, meter box & transformers		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Unattached to well rod		
Corrective Action:		Date:	

Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 241089 Type: WELL API Number: 123-08877 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI, the well is part of a 901 Order.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 09/30/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Plumbed to surface.

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On Tuesday 2-24-2026 at approximately 1250 hrs. I, Inspector Robbie Revas, Conducted an audit of the well scout card & related forms followed by an onsite inspection: Follow up to FIR Doc# 715801388. Operator: KP Kauffman Location # 318309 API #05-123-08877 Well name: Suckla-Brown Unit 16 County: Weld Weather: Cloudy & clear Temp: 66* Location: Dry While there, I observed a wellsite, SI at the time of inspection. During this inspection the following possible compliance issues were observed to have not been addressed: 606 Housekeeping: vegetation needs to be removed, CA 8-26-2025. Any corrective actions from previous Inspections that have not been addressed are still applicable See attached photos. A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.</p>	revasr	02/24/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715801966	Location photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7459951