

FORM
INSPRev
X/20

State of Colorado
Energy and Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/24/2026

Submitted Date:

02/24/2026

Document Number:

719001434

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
325964 _____ GARCIA, CHARLES _____ 2A Doc Num: _____

Operator Information:

ECMC Operator Number: _____ 10749 _____
Name of Operator: SIMCOE LLC _____
Address: 1199 MAIN AVE SUITE 101 _____
City: _____ DURANGO _____ State: _____ CO _____ Zip: _____ 81301 _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 _____ Number of Comments
0 _____ Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
		ehsinspections@machnr.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215642	WELL	PR	06/01/2023	CBM	067-07247	HARTMAN 1	PR

General Comment:

Inspection Report Summary
On 2/24/26 | Inspector Charles Garcia
conducted an on-site inspection.
Location: HARTMAN 1
Operator: Simcoe LLC
API#: 067-07247
County: LaPlata

Location

Overall Good:

Signs/Marker:			
Type	OTHER		
Comment:	LOCATION SIGN AT ENTRANCE		
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:	Contact # 970-247-6916 Emergency #911	
Corrective Action:		Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No
 Comment:
 Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	SAFETY WIRE MESH		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	CATTLE PANELS		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 5		
Comment:	TELEMETRY EQUIPMENT ELECTRIC PANELS		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	ELECTRIC		
Corrective Action:		Date:	
Type: Other	# 1		

Comment: METER HOUSE CALIBRATION IN COMPLIANCE			
Corrective Action:			Date:
Type: Other	# 1		
Comment: WELLHEAD			
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719001435	LOCATION PICTURES	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7460061