

Inspection Photos

Location Name: LARAMIE ENERGY LLC SHELL 0797-03B Pad

Location ID: 335482



Photo # 2788 From entrance to location



Photo # 2789 From entrance to location

Inspection Photos

Location Name: LARAMIE ENERGY LLC SHELL 0797-03B Pad

Location ID: 335482




Photo # 2790 Location

Photo # 2791 Location

Inspection Photos

Location Name: LARAMIE ENERGY LLC SHELL 0797-03B Pad

Location ID: 335482



Photo # 2792 Location



Photo # 2793 Location

Inspection Photos

Location Name: LARAMIE ENERGY LLC SHELL 0797-03B Pad

Location ID: 335482



Photo # 2794 Location



Photo # 2795 Location

Inspection Photos

Location Name: LARAMIE ENERGY LLC SHELL 0797-03B Pad

Location ID: 335482



Photo # 2796 Location



Photo # 2797 Location

Inspection Photos

Location Name: LARAMIE ENERGY LLC SHELL 0797-03B Pad

Location ID: 335482



Photo # 2798 Location



Photo # 2799 Location

Inspection Photos

Location Name: LARAMIE ENERGY LLC SHELL 0797-03B Pad

Location ID: 335482



Photo # 2800 Unused flowline lacks lockout tagout (OOSLAT)



Photo # 2801 Unused flowline lacks lockout tagout (OOSLAT)

Inspection Photos

Location Name: LARAMIE ENERGY LLC SHELL 0797-03B Pad

Location ID: 335482



Photo # 2802 PRV vent lines do not comply with CECMC pressure safety device rules



Photo # 2803 PRV vent lines do not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: LARAMIE ENERGY LLC SHELL 0797-03B Pad

Location ID: 335482



Photo # 2804 PRV vent line does not comply with CECMC pressure safety device rules

Photo # 2805 PRV vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: LARAMIE ENERGY LLC SHELL 0797-03B Pad

Location ID: 335482



Photo # 2806 Rupture disc vent line does not comply with CECMC pressure safety device rules



Photo # 2807 PRV vent line does not comply with CECMC pressure safety device rules