

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/12/2026

Submitted Date:

02/18/2026

Document Number:

710500729

**FIELD INSPECTION FORM**

Loc ID 439554 Inspector Name: Sanchez, Chris On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10412  
Name of Operator: AUSCO PETROLEUM INC  
Address: 113 N SANTA FE AVENUE  
City: FLORENCE State: CO Zip: 81226

**Findings:**

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Harkins, Liz	719-429-4513	Lharkins@austinexploration.com	<a href="#">All Inspections</a>
Hart, Tim	309-999-5420	thart@fremontpetroleum.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
439553	WELL	PA	08/04/2025	OW	043-06228	Marco Polo 1	EI

**General Comment:**

This is a follow up environmental inspection for Marco Polo 1, well location located in Fremont County, Colorado.

API # 05-043-06228  
Location ID 439554, Pathfinder C-18 4  
Remediation Project # 41047

**Inspected Facilities**

Facility ID: 439553 Type: WELL API Number: 043-06228 Status: PA Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Environmental**

**Spill/Remediation:**

Comment: This is a follow up Environmental Inspection for remediation project # 41047. At the time of inspection, an open excavation was observed at the wellhead. Cattle Panels were set in place securing the excavation.

Initial Form 27-I was submitted on 06/18/2025 and approved on 06/30/2025. The approved reporting schedule was identified as 90 days after receipt of analytical. Form 6-S document no. 404300609 indicates the well was cut and capped on 8/04/2025.

Operator shall submit Supplemental Form 27-S in accordance with the reporting schedule approved in Form 27-I document no. 404245195.

Corrective Action:	In accordance with Rule 913.e., Operator will adopt a quarterly reporting schedule (every 90 days) Previously assigned corrective action date shall apply 01/30/2026	Date: 01/30/2026
--------------------	---	------------------

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**ECMC Comments**

Comment	User	Date
All ongoing/unaddressed comments, Corrective Actions (CAs) and Conditions of Approval (COAs) from previous Forms remain applicable.	sanchezcc	02/18/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404549297	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7453915">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7453915</a>
710500730	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7453912">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7453912</a>