

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/12/2026

Submitted Date:

02/18/2026

Document Number:

710500731

FIELD INSPECTION FORM

Loc ID 443255 Inspector Name: Sanchez, Chris On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10412
Name of Operator: AUSCO PETROLEUM INC
Address: 113 N SANTA FE AVENUE
City: FLORENCE State: CO Zip: 81226

Findings:

- 7 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Harkins, Liz	719-429-4513	Lharkins@austinexploration.com	All Inspections
Hart, Tim	309-999-5420	thart@fremontpetroleum.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
443256	WELL	PR	08/01/2020	OW	043-06229	Magellan 1	EI

General Comment:

[This is a follow up Environmental Inspection for Magellan 1, well location located in Fremont County, Colorado.](#)
[API # 05-043-06229](#)
[Location ID 443255, Pathfinder C-18 2](#)

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Well Placard located at the wellhead, well name is not legible Install sign to comply with Rule 605.g.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:				
Type	Area	Volume		
Other	WELLHEAD			
Comment:	At the time of inspection well was not pumping. It is unknown if the leak observed at the wellhead on 1/14/2026 was repaired. on 1/14/2026: At the time of inspection, an audible gas leak was noted at the wellhead. ECMC staff messaged Ausco Petroleum Emergency Contact, (Liz Harkins), regarding the suspected gas leak. Original CA date shall apply 1/16/2026			
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date:	01/16/2026
Lube Oil	Pump Jack			
Comment:	At the time of inspection, oily liquids were observed on the base of the pumping unit adjacent to the engine skid. Original CA date of 2/02/2026 shall apply			
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date:	02/02/2026

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:	Yes/No		
Comment:			
Corrective Action:		Date:	

Flaring:	Type	
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 443256 Type: WELL API Number: 043-06229 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
All ongoing/unaddressed comments, Corrective Actions (CAs) and Conditions of Approval (COAs) from previous Forms remain applicable.	sanchezcc	02/18/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404549302	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7453917
710500732	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7453913