

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/12/2026

Submitted Date:

02/18/2026

Document Number:

710500733

FIELD INSPECTION FORM

Loc ID: 322270 Inspector Name: Sanchez, Chris On-Site Inspection: 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 17210
Name of Operator: CINNAMON CREEK OIL & GAS INC
Address: P O BOX 544
City: WALSH State: CO Zip: 81090

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 7 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Mills, Rick	719-324-5630/719-353-2523	rickmills000@gmail.com	All Inspections
Mills, Hellen		helening1221@yahoo.com	All Inspections
Waggoner, Kyle		kyle.waggoner@state.co.us	
Beardslee, Tom		tom.beardslee@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210093	WELL	PR	11/01/2022	OW	043-40030	ANDERSON 1	EI

General Comment:

This is an Environmental Inspection for the Anderson 1 well location located in Fremont County Colorado

Anderson 1
Location ID: 322270
API #: 05-043-40030

Location

Overall Good:

Signs/Marker:			
Type			
Comment:	Placard located at Tank Battery		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:		Date:	

Good Housekeeping:			
Type	OTHER		
Comment:	At the time of inspection, oil stained soils were observed at the truck loadout.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. Properly dispose of oily waste in accordance with 905.e.	Date:	03/06/2026

Overall Good:

Spills:			
Type	Area	Volume	
Crude Oil			
Comment:	At the time of inspection, oil stained soils were observed along the well location access road.		
Corrective Action:	Properly dispose of oily waste in accordance with 905.e.		Date: 03/05/2026
Lube Oil	Pump Jack		
Comment:	At the time of inspection, impacted materials were observed within the frame of the Pump Jack at the rear of the unit.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. Properly dispose of oily waste in accordance with 905.e.		Date: 03/06/2026

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 210093 Type: WELL API Number: 043-40030 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404549524	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7454183
710500734	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7454180