

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/18/2026

Submitted Date:

02/18/2026

Document Number:

716301977

FIELD INSPECTION FORM

Loc ID 333948 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10705
Name of Operator: EVERGREEN NATURAL RESOURCES LLC
Address: 1775 SHERMAN ST. #2775
City: DENVER State: CO Zip: 80203

Findings:

- 11 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Distribution, Evergreen	719-846-7898	cogcc.evergreen@enrllc.com	All Inspections
D DYKE, TRACY	719-846-7898	tracy.dyke@enrllc.com	Insp. w/ca's

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277923	WELL	PR	07/24/2005	CBM	071-08393	OINK OINK 14-36 TR	PR
277925	WELL	TA	05/25/2012	OBW	071-08394	OINK OINK 14-36	TA

General Comment:

"This is a field audit of the scout card, related documents and the location."

Location

Overall Good:

Signs/Marker:

	Type OTHER		
Comment:	PHOTO 2: ACCORDING TO ECMC RECORDS THE API # FOR THE OINK OINK 14-36 TR IS 05-071-08393 NOT 08383.		
Corrective Action:	POST SIGN PER RULE 605.	Date:	03/17/2026

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

						corrective date
Type: Deadman # & Marked	# 4					
Comment:						
Corrective Action:						Date:
Type: Vertical Separator	# 1					
Comment:						
Corrective Action:						Date:
Type: Ancillary equipment	# 1					
Comment:						
Corrective Action:						Date:
Type: Bradenhead	# 1					
Comment:	IS ACCESSABLE					
Corrective Action:						Date:
Type: Gas Meter Run	# 1					
Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.					
Corrective Action:						Date:
Type: Progressive Cavity	# 1					
Comment:						
Corrective Action:						Date:
Type: Prime Mover	# 1					
Comment:						
Corrective Action:						Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 277923 Type: WELL API Number: 071-08393 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 11/10/2011 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: FORM 4 #2319084

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 277925 Type: WELL API Number: 071-08394 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: WELL HAS BEEN CONVERTED TO A SEISMIC MONITOR WELL FORM 4 #400701995

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 11/10/2011 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: FORM 4 #2319083

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Comment: <input style="width:90%;" type="text"/> Corrective Action: <input style="width:90%;" type="text"/>						Date: _____
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						
Type: <u>Produced Water</u>	Lined: <u>NO</u>	Pit ID: <u>281069</u>	Lat: <u>37.208428</u>	Long: <u>-104.847537</u>		
Reference Point: _____	Other: _____	Length: _____	Width: _____			
Lining:						
Liner Type: _____			Liner Condition: _____			
Comment: <input style="width:95%;" type="text"/>						Date: _____
Corrective Action <input style="width:95%;" type="text"/>						
Fencing:						
Fencing Type: <u>None</u>			Fencing Condition: _____			
Comment: <input style="width:95%;" type="text"/>						Date: _____
Corrective Action <input style="width:95%;" type="text"/>						
Netting:						
Netting Type: _____			Netting Condition: _____			
Comment: <input style="width:95%;" type="text"/>						Date: _____
Corrective Action <input style="width:95%;" type="text"/>						
Anchor Trench Present: <u>NO</u>	Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>YES</u>				
Comment: <input style="width:95%;" type="text"/>						Date: _____
Corrective Action <input style="width:95%;" type="text"/>						

ECMC Comments		
Comment	User	Date
<p style="color: blue; margin: 0;"> ECMC Inspection Report Summary Date: 2/17/2026 Time: 09:53 Operator: EVERGREEN NATURAL RESOURCES LLC 10705 Location: OINK OINK 14-36 TR API# 05-071-08393 County: Las Animas County. While there, I ECMC staff performed a field audit of the scout card, related documents and the location. During the audit the following possible compliance issues were observed: API # INCORRECT FOR TR WELL, RULE 605, CA DUE DATE 3/17/2026 A follow-up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules. </p>	beardslt	02/18/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404548924	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7453617
716301979	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7453610