

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/10/2026

Submitted Date:

02/18/2026

Document Number:

719500906

FIELD INSPECTION FORM

Loc ID 335590 Inspector Name: Morris, Matthew On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10844
Name of Operator: QB ENERGY OPERATING LLC
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

Findings:

- 11 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Energy, QB		ecmc.inspections@qb-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277753	WELL	PR	12/01/2018	GW	045-10769	N. PARACHUTE WF07D I25 596	PR
277755	WELL	PR	03/01/2025	GW	045-10767	N. PARACHUTE WF02D I25 596	PR
277756	WELL	PR	12/01/2018	GW	045-10766	N. PARACHUTE WF08B I25 596	PR
277757	WELL	PR	12/01/2018	GW	045-10765	N. PARACHUTE WF08D I25 596	PR
277758	WELL	PR	12/01/2018	GW	045-10764	N. PARACHUTE WF01D I25 596	PR

General Comment:

This is a field audit of the location, scout card, and related documents.

On 2/11/2026 at approximately 14:35, Compliance Inspector Matthew Morris conducted a follow-up audit at QB ENERGY OPERATING LLC, N. Parachute/WF I25 596 at Location ID #335590 in Garfield County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

Location

Overall Good:

Signs/Marker:

Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	One sign is posted for all wells on location. Stamped steel tags hung on the wells are missing required information (API number) and are not conspicuously posted.		
Corrective Action:	Comply with CECMC Signage Requirements.	Date:	03/19/2026

Emergency Contact Number:

Comment: 911/(970)285-2615

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Concrete barriers		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Pipe rails		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Pipe rails installed at gas meters.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Concrete barriers installed at gas lift and ancillary equipment.		
Corrective Action:		Date:	

Equipment:

Type: Ancillary equipment	# 2		corrective date
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Line heater		
Corrective Action:		Date:	
Type: Gas Meter Run	# 5		

Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 5		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 4		
Comment:	Gas lift		
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 277753 Type: WELL API Number: 045-10769 Status: PR Insp. Status: PR

Producing Well

Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 277755 Type: WELL API Number: 045-10767 Status: PR Insp. Status: PR

Producing Well

Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 277756 Type: WELL API Number: 045-10766 Status: PR Insp. Status: PR

Producing Well

Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 277757 Type: WELL API Number: 045-10765 Status: PR Insp. Status: PR

Producing Well

Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 277758 Type: WELL API Number: 045-10764 Status: PR Insp. Status: PR

Producing Well

Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						
		Culverts				
		Gravel				
		Compaction				
				Material Handling And Spill Prevention		
Berms						
		Check Dams				
Compaction						
		Ditches				
Ditches						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>During the audit, the following compliance issue(s) were observed:</p> <p>1) One sign is posted for all wells on location. Stamped steel tags hung on the wells are missing required information (API number) and are not conspicuously posted.</p> <p>A follow-up on this site audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p>	morrism	02/18/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404550076	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7454792
719500907	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7454788