

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/12/2026

Submitted Date:

02/18/2026

Document Number:

710500725

FIELD INSPECTION FORM

Loc ID: 334402 Inspector Name: Sanchez, Chris On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10417
Name of Operator: INCREMENTAL OIL & GAS (FLORENCE) LLC
Address: 113 N SANTA FE AVE
City: FLORENCE State: CO Zip: 81226

Findings:

- 5 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Hart, Tim	309-999-5420	thart@fremontpetroleum.com	All Inspections
Harkins, Liz	719-429-4513	Lharkins@austineexploration.com	All Inspections
Beardslee, Tom		tom.beardslee@state.co.us	
Waggoner, Kyle		kyle.waggoner@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295425	WELL	PA	11/02/2022	GW	043-06157	APACHE 33B-20	EI
334402	LOCATION	CL			-	GOLDEN-619S69W 20NWSE	EI

General Comment:

This is a follow up environmental inspection for the Apache 33B - 20 well location located in Fremont County, Colorado.

Apache 33B – 20
API #: 05-043-06157
Location ID: 334402
Remediation project # 37653

Location

Lease Road:			
Type	Access		
comment:	Location is not accessible during normal business hours.		
Corrective Action:	Provide key, combinations, or alternate method of access to comply with rule 204.	Date:	02/27/2026

Overall Good:

Emergency Contact Number:	
Comment:	<input style="width: 90%;" type="text"/>
Corrective Action:	<input style="width: 90%;" type="text"/>
Date:	_____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 295425 Type: WELL API Number: 043-06157 Status: PA Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 334402 Type: LOCATION API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spill/Remediation:

Comment: This is a follow up remediation inspection for Remediation Project # 37653.

ECMC Staff was not able to access the location at the time of inspection due to an issue with the present surface owner. Per FIR document no. 710500510: Environmental Staff contacted Dale Lanskey, Incremental Oil and Gas who worked with the Lease Operator to identify the location. Per Dale and Incremental Lease Operator, the subject land currently has an access issue due to the Surface Owner restricting access. Staff took note of the Posted Private Property sign at the entrance gate.

At the time of inspection, Quarterly Reporting for Remediation Project 37653 was beyond the 90-day reporting window in accordance with Rule 913.e.

The last quarterly update for Remediation Project # 37653 was received on 6/26/2025. A quarterly update was due September 24, 2025.

Corrective Action: Previously assigned corrective action date shall apply 01/29/2026 Date: 01/29/2026

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404549153	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7453811
710500726	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7453809