

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/23/2026

Submitted Date:

02/26/2026

Document Number:

713401261

**FIELD INSPECTION FORM**

Loc ID 398876 Inspector Name: Popejoy, Dusty On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 76950  
Name of Operator: SCHUMACHER\* JOHN  
Address: \_\_\_\_\_  
City: DENVER State: CO Zip: 80203

**Findings:**

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Chaivre, Annie		annie.chaivre@state.co.us	
Roberts, James		j75rober@blm.gov	
Haverkamp, Curtis		curtis.haverkamp@state.co.us	
Kirschner, Steven		steven.kirschner@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Heil, John		john.heil@state.co.us	
Katz, Aaron		aaron.katz@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232299	WELL	PA	05/01/1962	DA	103-40088	USA--COLO 06412 2-G	PA

**General Comment:**

This is a Field Inspection/audit of the scout card, related documents and the location.  
No operator contact information in the CECMC database.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	LOCATION		
Comment:	Livestock/Barbed wire		
Corrective Action:		Date:	

**Venting:**

Yes/No	YES		
Comment:	Observed plugged and abandoned well actively venting gas during inspection. Optical Gas Imaging (FLIR) confirmed continuous venting from the well. Please refer to FLIR camera videos		
Corrective Action:	Well is to be re-entered and replugged to assure that all sources of hydrocarbons are isolated appropriately and potential to emit is eliminated. Form 6 Notice of Intent should be filed by March 26, 2026. It is expected that work is completed and reported by August 26, 2026.	Date:	03/26/2026

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 232299 Type: WELL API Number: 103-40088 Status: PA Insp. Status: PA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Optical Gas Imaging Survey**

Survey Type: Complaint

Current Operations:  Production  Workover  Flowback  Referred to APCD

GPS(entrance of location): Lat: 40.087346 Long: 108.776706

Wind: Calm Speed: \_\_\_\_\_ (mph) Direction From: West Weather: Clear Temperature: 42 (F)

Assisting Staff: \_\_\_\_\_ Camera #: 1

Visible Smoke  Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
11:40	AM	11:45	AM	

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date:

**ECMC Comments**

Comment	User	Date
<p><a href="#">CECMC Inspection/Audit Report Summary</a></p> <p>On 02/23/2026 at approximately 11:35 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection/audit for a complaint, #200442262 at SCHUMACHER* JOHN USA--COLO 06412 #2-G well at Location ID #398876 in Rio Blanco County, Colorado.</p> <p>This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority, NSO, Density Habitat regulations. Location is approximately 17 yards east of Highway 139 between mile marker 72 and Highway 64.</p> <p>While there, I observed plugged and abandoned well actively venting gas Optical Gas Imaging (FLIR) confirmed continuous venting from the well.</p> <p>During the inspection/audit, the following compliance issues were observed:</p> <p>1. Venting - Plugged and abandoned well actively venting gas during inspection. Optical Gas Imaging (FLIR) confirmed continuous venting from the well with a CA date of 03/26/2026</p> <p>A follow-up on this site inspection/audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p> <p>This is a summary of inspection/audit report.</p>	popejoyd	02/25/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713401262	713401261 Inspection-Audit Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7462116">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7462116</a>
713401263	713401261 Inspection-Audit FLIR video	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7462117">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7462117</a>
713401264	713401261 Inspection-Audit FLIR video	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7462118">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7462118</a>
713401265	713401261 Inspection-Audit FLIR video	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7462119">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7462119</a>