

Inspection Photos

Location Name: Lorencito 12-2-34-66

Location ID: 307588

API #: 05-071-06647



Photo 1: Well Placard

Photo 2: Wellhead and equipment

Inspection Photos

Location Name: Lorencito 12-2-34-66

Location ID: 307588

API #: 05-071-06647



Photo 3: Pit Facility ID 261259



Photo 4: Meter house, disconnected flowlines

Inspection Photos

Location Name: Lorencito 12-2-34-66

Location ID: 307588

API #: 05-071-06647



Feb 26, 2026 at 9:40:31 AM
+37.110158,-104.772018
ECMC

Photo 5: Hole in pit liner



Feb 26, 2026 at 9:39:59 AM
+37.110239,-104.772088
ECMC

Photo 6: Hole in pit liner