

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/26/2026

Submitted Date:

02/26/2026

Document Number:

713302515

**FIELD INSPECTION FORM**

Loc ID 327796 Inspector Name: Kester, Michael On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 47120  
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
Address: P O BOX 173779  
City: DENVER State: CO Zip: 80217-

**Findings:**

- 9 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, KerrMcGee	970-515-1500	ECMCInspections@Oxy.com	<a href="#">all inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
247364	WELL	TA	03/14/2017	OW	123-15161	FRANK H21-15	TA

**General Comment:**

[Follow up well site inspection](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	good		
Corrective Action:			Date:

**Emergency Contact Number:**

Comment:			
Corrective Action:			Date: _____

**Good Housekeeping:**

Type	DEBRIS		
Comment:	wind terrible day before inspection movin every tumble weed in county		
Corrective Action:			Date:

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	pipe panels		
Corrective Action:			Date:

**Equipment:**

Type: Bradenhead	# 1				corrective date
Comment:	piped to surface				
Corrective Action:					Date:

**Venting:**

Yes/No	NO			
Comment:				
Corrective Action:				Date:

**Flaring:**

Type				
Comment:				
Corrective Action:				Date:

**Inspected Facilities**

Facility ID: 247364 Type: WELL API Number: 123-15161 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Form 6A on file doc 403108165, 7-22-2022 well head disconnected with fittings plugged

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 01/29/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: None  
 End Surf Csg Pressure: 0

Comment: submit report

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<p><u>Audit of scout card and related documents</u></p> <p><u>Follow up inspection as per Doc # 716201915, corrective actions appeared to have been addressed</u></p> <p><u>Form 6A on file doc 403108165, 7-22-2022, well head disconnected with fittings plugged</u></p> <p><u>This inspection does not nullify any orders or NOAV from the ECMC</u></p>	kesterm	02/26/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713302516	site pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7463210">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7463210</a>