

**ECMC Inspection Photos - KP Kauffman**  
**Location: Facility 8 at Maggie Norden B 1**  
**Date 02/26/2026**



**(1) 4" CS off location flowline (Facility 8 consolidation) and (1) 2" CS gas line (OOS) exposed in excavation at point of release (40.049530, -104.866933); poly liner under pipes.**



**West bell hole excavation @ 40.049530, -104.867144 and Facility 8 off location flowline(s) exposed.  
View looking east toward fenced spill/ release excavation.**

**ECMC Inspection Photos - KP Kauffman**  
**Location: Facility 8 at Maggie Norden B 1**  
**Date 02/26/2026**



**Corrosion hole identified on the bottom of the 4" Facility 8 consolidation flowline appears to be the result of internal corrosion. External pipe coating has been blown out around hole in area of release.**



**Location of corrosion hole found on bottom of 4" Facility 8 flowline pipe is indicated with placement of finger.**

**ECMC Inspection Photos - KP Kauffman**  
**Location: Facility 8 at Maggie Norden B 1**  
**Date 02/26/2026**



**East bell hole excavation @ 40.049530, -104.866117.**  
**Flowline pipe repair work in progress; approximately 300' of 3" SDR 11 HDPE rolled pipe being slip lined through failed section of 4" flowline pipe. View west toward spill/ release area and WCR 21.**

**Closer view of stinging/ slip lining flowline repair work being completed. (3) historical flowlines exposed in east bellhole excavation; (1) 2" gas line, (1) 3" fiberglass and (1) 1" orange poly line found. Per KPK field personnel historical lines found are out of service with cut ends to be capped/ sealed prior to backfill.**