

Inspection Photos  
Simcoe – Joe Hotter 1  
API # 05-067-06964

Inspector Name: James Blair. Inspection Date: 02/25/2026  
Inspection Doc #: 721100157



01. Well Sign was fallen over, is not secured, stood up for picture, layed back down.

Inspection Photos  
Simcoe – Joe Hotter 1  
API # 05-067-06964

Inspector Name: James Blair. Inspection Date: 02/25/2026  
Inspection Doc #: 721100157



02. Wellhead is surrounded by cattle panel fence. Sign is lying face down.

Inspection Photos  
Simcoe – Joe Hotter 1  
API # 05-067-06964


Inspector Name: James Blair. Inspection Date: 02/25/2026  
Inspection Doc #: 721100157



03. Wellhead. Bradenhead is accessible.

Inspection Photos  
Simcoe – Joe Hotter 1  
API # 05-067-06964

Inspector Name: James Blair. Inspection Date: 02/25/2026  
Inspection Doc #: 721100157



**04. Vertical heated separator. Bird protector on stack.**

Inspection Photos  
Simcoe – Joe Hotter 1  
API # 05-067-06964

Inspector Name: James Blair. Inspection Date: 02/25/2026  
Inspection Doc #: 721100157



05. Vertical heated separator inside cattle panel fence. Telemetry and solar behind to left.

Inspection Photos  
Simcoe – Joe Hotter 1  
API # 05-067-06964

Inspector Name: James Blair. Inspection Date: 02/25/2026  
Inspection Doc #: 721100157



06. Inside vertical heated separator.

Inspection Photos  
Simcoe – Joe Hotter 1  
API # 05-067-06964

Inspector Name: James Blair. Inspection Date: 02/25/2026  
Inspection Doc #: 721100157



07. Compressor behind sound wall. Motor was running at time of inspection.

Inspection Photos  
Simcoe – Joe Hotter 1  
API # 05-067-06964

Inspector Name: James Blair. Inspection Date: 02/25/2026  
Inspection Doc #: 721100157



8. Meter run and 3" flow lines. Tumbleweed dead vegetative debris is accumulating in the corner of the cattle panel fence, but is more than 25 feet from fired equipment.

Inspection Photos  
 Simcoe – Joe Hotter 1  
 API # 05-067-06964

Inspector Name: James Blair. Inspection Date: 02/25/2026  
 Inspection Doc #: 721100157

DATE/TESTER	METER TESTED	ORIFICE PLATE		GAS SAMPLE	BASIC/DETAIL INSP.
		INSPECT	SIZE		
7-28-20 <sup>LP</sup>	YES	YES	1.375	YES	—
7-27-21 <sup>TD</sup>	YES	YES	1.375	YES	—
7-11-22 <sup>KC</sup>	YES	YES	1.375 SID	YES	—
7-6-23 <sup>KC</sup>	YES	YES	1.375 SID	YES	—
7-29-24 <sup>KC</sup>	YES	YES	1.375 SID	YES	—
7-8-25 <sup>KC</sup>	YES	YES	1.375 SID	YES #419	—

Energy & Carbon Management Commission  
 La Plata County  
 +37.196349,-107.846781  
 195° S  
 Feb 25, 2026 at 11:58:41 AM

9. Meter calibration card dated 07/08/2025.

Inspection Photos  
Simcoe – Joe Hotter 1  
API # 05-067-06964

Inspector Name: James Blair. Inspection Date: 02/25/2026  
Inspection Doc #: 721100157



10. Produced water tank. Sign mostly peeled off and not legible and paint is inadequate.

Inspection Photos  
Simcoe – Joe Hotter 1  
API # 05-067-06964

Inspector Name: James Blair. Inspection Date: 02/25/2026  
Inspection Doc #: 721100157



11. View looking NW along south margin of pad. Telemetry and solar in foreground. Compressor behind sound wall in background.

Inspection Photos  
Simcoe – Joe Hotter 1  
API # 05-067-06964

Inspector Name: James Blair. Inspection Date: 02/25/2026  
Inspection Doc #: 721100157



12. Access road looking to the northeast to highway 550, adjacent to site.

Inspection Photos  
Simcoe – Joe Hotter 1  
API # 05-067-06964

Inspector Name: James Blair. Inspection Date: 02/25/2026  
Inspection Doc #: 721100157



13. Access road to well pad looking west.

Inspection Photos  
Simcoe – Joe Hotter 1  
API # 05-067-06964

Inspector Name: James Blair. Inspection Date: 02/25/2026  
Inspection Doc #: 721100157



14. View of well pad from entrance gate. Gate was open at time of inspection.

Inspection Photos  
Simcoe – Joe Hotter 1  
API # 05-067-06964

Inspector Name: James Blair. Inspection Date: 02/25/2026  
Inspection Doc #: 721100157



15. View of well pad looking due north from wellhead.

Inspection Photos  
Simcoe – Joe Hotter 1  
API # 05-067-06964

Inspector Name: James Blair. Inspection Date: 02/25/2026  
Inspection Doc #: 721100157



16. View looking due south from wellhead.

Inspection Photos  
Simcoe – Joe Hotter 1  
API # 05-067-06964

Inspector Name: James Blair. Inspection Date: 02/25/2026  
Inspection Doc #: 721100157



17. View looking due west from wellhead.

Inspection Photos  
Simcoe – Joe Hotter 1  
API # 05-067-06964

Inspector Name: James Blair. Inspection Date: 02/25/2026  
Inspection Doc #: 721100157



18. View looking due east from wellhead. US HWY 550 is just east of location. Barbed wire and mesh fence is visible.