


Inspection Photos
Simcoe/ Mach Natural Resources – JOE HOTTER #2
API # 05-067-08708
Inspector Name: James Blair. Inspection Date: 02/26/2026
Inspection Doc #: 721100166



1. Well Sign. 24 Hour Contact: 970-247-6619, Emergency 911.

Inspection Photos
Simcoe/ Mach Natural Resources – JOE HOTTER #2
API # 05-067-08708
Inspector Name: James Blair. Inspection Date: 02/26/2026
Inspection Doc #: 721100166



2. Well location. Mud and ruts are present from recent snowfall and warm temperatures. A workover rig was on site the day before.

Inspection Photos
Simcoe/ Mach Natural Resources – JOE HOTTER #2
API # 05-067-08708
Inspector Name: James Blair. Inspection Date: 02/26/2026
Inspection Doc #: 721100166



03. Wellhead and electric drive progressive cavity pump along with electrical controls.

Inspection Photos
Simcoe/ Mach Natural Resources – JOE HOTTER #2
API # 05-067-08708
Inspector Name: James Blair. Inspection Date: 02/26/2026
Inspection Doc #: 721100166




4. Wellhead, progressive cavity pump, and electrical controls behind cattle panel fence.

Inspection Photos
Simcoe/ Mach Natural Resources – JOE HOTTER #2
API # 05-067-08708
Inspector Name: James Blair. Inspection Date: 02/26/2026
Inspection Doc #: 721100166



05. PBV tank and secondary containment.

Inspection Photos
 Simcoe/ Mach Natural Resources – JOE HOTTER #2
 API # 05-067-08708
 Inspector Name: James Blair. Inspection Date: 02/26/2026
 Inspection Doc #: 721100166



6. Meter run calibration card. 7/15/25 date.

Inspection Photos
Simcoe/ Mach Natural Resources – JOE HOTTER #2
API # 05-067-08708
Inspector Name: James Blair. Inspection Date: 02/26/2026
Inspection Doc #: 721100166



7. Horizontal heated separator.

Inspection Photos
Simcoe/ Mach Natural Resources – JOE HOTTER #2
API # 05-067-08708
Inspector Name: James Blair. Inspection Date: 02/26/2026
Inspection Doc #: 721100166



8. Inside horizontal heated separator.

Inspection Photos
Simcoe/ Mach Natural Resources – JOE HOTTER #2
API # 05-067-08708
Inspector Name: James Blair. Inspection Date: 02/26/2026
Inspection Doc #: 721100166



9. Location looking east. Note ruts in foreground from workover a few days prior.

Inspection Photos
Simcoe/ Mach Natural Resources – JOE HOTTER #2
API # 05-067-08708
Inspector Name: James Blair. Inspection Date: 02/26/2026
Inspection Doc #: 721100166



10. Drainage ditch separates location from ag field.

Inspection Photos
Simcoe/ Mach Natural Resources – JOE HOTTER #2
API # 05-067-08708
Inspector Name: James Blair. Inspection Date: 02/26/2026
Inspection Doc #: 721100166



11 Ruts on pad. Ag fields immediately adjacent.

Inspection Photos
Simcoe/ Mach Natural Resources – JOE HOTTER #2
API # 05-067-08708
Inspector Name: James Blair. Inspection Date: 02/26/2026
Inspection Doc #: 721100166



12. Access road looking towards well location.

Inspection Photos
Simcoe/ Mach Natural Resources – JOE HOTTER #2
API # 05-067-08708
Inspector Name: James Blair. Inspection Date: 02/26/2026
Inspection Doc #: 721100166



13. Access road from well location looking east.