

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/25/2026

Submitted Date:

02/27/2026

Document Number:

721100156

FIELD INSPECTION FORM

Loc ID 326656 Inspector Name: Blair, Jamie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10749
Name of Operator: SIMCOE LLC
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301

Findings:

- 13 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Natural, Mach		ehsinspections@machnr.com	
Labowskie, Steve		steve.labowskie@state.co.us	
Blair, Jamie		jamie.blair@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261488	WELL	PR	11/23/2021	CBM	067-08639	TILLMAN BURCH 2	PR

General Comment:

On Tuesday, February, 24, 2026 at 12:20 PM southwest compliance specialist Jamie Blair performed a compliance inspection and audit on the Tillman Burch 2 well. Conditions were wet and muddy at the time of the inspection due to recent snow and warm temperatures. Workover rig in some photos is on neighboring pad not related to this well or operator. Paint on tank inadequate.

Location			
Lease Road:			
Type	Access		
comment:	Muddy and rutted at time of inspection due to recent snow and warm temperature. A workover rig and associated vehicles on an adjacent pad for a different operator that used the same access road.		
Corrective ActionL		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Well sign Photo 1.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	24 hour - 970-247-6916. Emergency - 911.		
Corrective Action:		Date:	
Good Housekeeping:			
Type	WEEDS		
Comment:	Some vegetative debris from previous growth season was present on pad, but not near fired equipment.		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No _____			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	OTHER		
Comment:	steel pipe barricades around wellhead, pump jack, separator, and tank.		
Corrective Action:		Date:	
Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Partially submerged at time of inspection.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		

Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	wellhead		
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	gas		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Calibration Date 7/16/2025		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER		OTHER	PBV STEEL		37.122400,-107.663591
Comment:	Paint is inadequate. Photo 4.				
Corrective Action:	Inspect, maintain and repair tanks to comply with rule 609.b.				Date: 03/30/2026

Paint

Condition	Inadequate
Other (Content)	Produced water with natural gas.
Other (Capacity)	21 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type	
Comment:	

Corrective Action:

Date:

Inspected Facilities

Facility ID: 261488 Type: WELL API Number: 067-08639 Status: PR Insp. Status: PR

Producing Well

Comment: Pump jack moving at time of inspection.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 09/18/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment: Muddy and saturated at time of inspection due to seasonal conditions. Did not drive onto pad during inspection.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
	blairj1	02/27/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
721100169	photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7464048