

| | | | |
|---|---|------|---|
| FORM INSP Rev X/20 | State of Colorado Energy and Carbon Management Commission 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109 | | Inspection Date: <u>02/27/2026</u> Submitted Date: <u>02/27/2026</u> Document Number: <u>719001463</u> |
| FIELD INSPECTION FORM | | | |

Loc ID 326151 Inspector Name: GARCIA, CHARLES On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Status Summary:

THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

12 Number of Comments

0 Number of Corrective Actions

Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|-------|-----------------------------|---------|
| Labowskie, Steve | | steve.labowskie@state.co.us | |
| | | ehsinspections@machnr.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 215952 | WELL | PR | 08/01/2018 | CBM | 067-07558 | DWIGHT SOSSAMAN A 1 | PR |

General Comment:

[Inspection Report Summary](#)
 On 2/27/26 | Inspector Charles Garcia conducted an on-site inspection.
 Location: DWIGHT SOSSAMAN A 1
 Operator: Simcoe LLC
 API#: 067-07558
 County: LaPlata
 All prior CA's still stand.

Location

Overall Good:

| | | | |
|----------------------|---------------------------|--|-------|
| Signs/Marker: | | | |
| Type | OTHER | | |
| Comment: | LOCATION SIGN AT ENTRANCE | | |
| Corrective Action: | | | Date: |

| | | | |
|---------------------------|--|--|-------|
| Emergency Contact Number: | | | |
| Comment: | Contact # 970-247-6916 Emergency #911 | | |
| Corrective Action: | | | Date: |

Overall Good:

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No
 Comment:
 Multiple Spills and Releases?

| | | | |
|--------------------|-------------------------------|--|-------|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | CATTLE PANELS | | |
| Corrective Action: | | | Date: |
| Type | OTHER | | |
| Comment: | PC PUMP CATTLE PANELS | | |
| Corrective Action: | | | Date: |
| Type | OTHER | | |
| Comment: | ELECTRIC PANELS CATTLE PANELS | | |
| Corrective Action: | | | Date: |
| Type | SEPARATOR | | |
| Comment: | CATTLE PANELS | | |
| Corrective Action: | | | Date: |
| Type | LOCATION | | |
| Comment: | CHAIN LINK | | |
| Corrective Action: | | | Date: |

| | | | |
|--------------------------|-----------------|--|-----------------|
| Equipment: | | | corrective date |
| Type: Bradenhead | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Other | # 1 | | |
| Comment: | CATHODIC SYSTEM | | |
| Corrective Action: | | | Date: |
| Type: Progressive Cavity | # 1 | | |

| | | | |
|---------------------------------|--|--|-------|
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Flow Line | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Other | # 1 | | |
| Comment: | WELLHEAD | | |
| Corrective Action: | | | Date: |
| Type: Bird Protectors | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Vertical Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Prime Mover | # 1 | | |
| Comment: | ELECTRIC | | |
| Corrective Action: | | | Date: |
| Type: Ancillary equipment | # 3 | | |
| Comment: | TELEMETRY EQUIPMENT 2 ELECTRIC PANELS | | |
| Corrective Action: | | | Date: |

Venting:

| | | | |
|--------------------|--|--|-------|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | | |
|--------------------|--|--|-------|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Inspected Facilities

Facility ID: 215952 Type: WELL API Number: 067-07558 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 10/13/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |
| Compaction | Pass | Compaction | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 719001464 | LOCATION PICTURES | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7464527 |