

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/27/2026

Submitted Date:

02/27/2026

Document Number:

719001466

FIELD INSPECTION FORM

Loc ID: 326150 Inspector Name: GARCIA, CHARLES On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10749
 Name of Operator: SIMCOE LLC
 Address: 1199 MAIN AVE SUITE 101
 City: DURANGO State: CO Zip: 81301

Findings:

10 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
		ehsinspections@machnr.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215951	WELL	PR	10/01/1990	CBM	067-07557	NEVA DOVE A 1	PR

General Comment:

Inspection Report Summary
 On 2/26/26 | Inspector Charles Garcia
 conducted an on-site inspection.
 Location: NEVA DOVE A 1
 Operator: Simcoe LLC
 API#: 067-07557
 County: LaPlata
 All prior CA's still stand.

Location

Overall Good:

Signs/Marker:			
Type	OTHER		
Comment:	LOCATION SIGN AT ENTRANCE		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Contact # 970-247-6916 Emergency #911		
Corrective Action:		Date:	

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No
 Comment:
 Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	CATTLE PANELS		
Corrective Action:		Date:	
Type	OTHER		
Comment:	PC PUMP CATTLE PANELS		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	CHAIN LINK		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	ELECTRIC		
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	TELEMETRY EQUIPMENT 2 ELECTRIC PANELS		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	WELLHEAD		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		

Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	METER HOUSE CALIBRATION IN COMPLIANCE		
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:			
Corrective Action:			Date:
Type: Progressive Cavity	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 215951 Type: WELL API Number: 067-07557 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 10/13/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719001467	LOCATION PICTURES	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7464528