

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/27/2026

Submitted Date:

03/01/2026

Document Number:

711902913

FIELD INSPECTION FORM

Loc ID: 312299 Inspector Name: SCHURE, KYM On-Site Inspection: 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 83130
Name of Operator: STRACHAN EXPLORATION INC
Address: 992 S 4TH AVE SUITE 100-461
City: BRIGHTON State: CO Zip: 80601

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|------------------|--------------------------------|---------|
| Harms, Jason | (303) 330 - 1921 | jharms@strachanexploration.com | |
| Binschus, Chris | | chris.binschus@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 221131 | WELL | PR | 06/01/2023 | OW | 075-09257 | BANEY-STATE 16-3 | PR |

General Comment:

THIS IS AN AUDIT OF THE WELL FILE, SCOUT CARD AND RELATED DOCUMENTS.
LAST FIR 9-2-2025
THIS WELL IS PR, THE RELATED BATTERY IS ATTACHED TO THIS FIR FOR CA'S
STORMWATER EROSION CA CITED WITHIN THIS FIR - CONTACT ECMC RECLAMATION GROUP FOR DIRECTIVES #8) HRS.
REPAIR/INSTALL BMP'S SEE PHOTOGRAPHS ATTACHED

Location

| | | | |
|--------------------|---|--|------------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | STORMWATER EROSION MANAGEMENT - LEASE ROAD TO TANK BATTERY CONTACT ECMC RECLAMATION GROUP FOR DIRECTIVES - (48) HRS. TO REPAIR/INSTALL BMP'S SEE PHOTOGRAPHS ATTACHED | | |
| Corrective Action: | INSTALL OR REPAIR REQUIRED BMP'S PER RULE 1002 SERIES | | Date: 03/03/2026 |

Overall Good:

| | | | |
|----------------------|--------------|--|-------|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | SATISFACTORY | | |
| Corrective Action: | | | Date: |
| Type | BATTERY | | |
| Comment: | SATISFACTORY | | |
| Corrective Action: | | | Date: |

| | | | |
|----------------------------------|--------------|--|-------------|
| Emergency Contact Number: | | | |
| Comment: | SATISFACTORY | | |
| Corrective Action: | | | Date: _____ |

| | | | |
|---------------------------|--|--|-------|
| Good Housekeeping: | | | |
| Type | OTHER | | |
| Comment: | STORMWATER EROSION ON LEASE ROAD TO BATTERY SEE ATTACHED PHOTOGRAPHS AND COMPLY WITH RULE 1002 SERIES. CONTACT ECMC RECLAMATION GROUP FOR DIRECTIVES - (48) HRS. TO REPAIR | | |
| Corrective Action: | | | Date: |

Overall Good:

| Spills: | | | |
|----------------|------|--------|--|
| Type | Area | Volume | |

In Containment: No

Comment: NONE OBSERVED

Multiple Spills and Releases?

| | | | |
|--------------------|------------------------------------|--|-----------------|
| Equipment: | | | corrective date |
| Type: Other | # 0 | | |
| Comment: | NO CHANGE IN EQUIPMENT INVENTORIED | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---------------------------------|----------|------|---------|--------|
| | | | | | |
| Comment: | NO CHANGE IN TANK CONFIGURATION | | | | |
| Corrective Action: | | | | | Date: |

| | |
|--------------|--|
| Paint | |
| Condition | |

| | |
|------------------|--|
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficent | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| Yes/No | NO | | |
|--------------------|----|--|-------|
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | | |
|--------------------|--|--|-------|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Inspected Facilities

Facility ID: 221131 Type: WELL API Number: 075-09257 Status: PR Insp. Status: PR

Producing Well

Comment: OW

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

| Comment | User | Date |
|---|----------|------------|
| ROUTINE FIR - CA'S CITED WITHIN THIS DOCUMENT | schureky | 03/01/2026 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 711902917 | PHOTOGRAPHS | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7464668 |