

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/23/2026

Submitted Date:

02/23/2026

Document Number:

697012484

FIELD INSPECTION FORM

Loc ID 456966 Inspector Name: Peterson, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10737
Name of Operator: EWS 6 DJ BASIN LLC
Address: 2015 CLUBHOUSE DR SUITE 201
City: GREELEY State: CO Zip: 80634

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Silver, Randy		randy.silver@state.co.us	
Gage, Dave	(970) 590-6463	Dgage@expedition-water.com	Facility Manager EWS #3
Goddard, Jim		jgoddard@expedition-water.com	
Beasley, Nolan		nolan.beasley@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
456971	WELL	IJ	08/21/2024	DSPW	123-47689	EWS 6A	AC

General Comment:

Operator ceased injection operations while the inspector was on location.

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Flow Line	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead valve is exposed at surface.		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 456971 Type: WELL API Number: 123-47689 Status: IJ Insp. Status: AC

Underground Injection Control

UIC Violation: Operational Violation Maximum Injection Pressure: _____

UIC Routine

Inj./Tube:	Pressure or inches of Hg <u>2050 psig</u> (e.g. 30 psig or -30" Hg)	Previous Test Pressure <u>2125</u>	MPP _____
TC:	Pressure or inches of Hg <u>1500 psig</u>	Previous Test Pressure <u>0</u>	Inj Zone: <u>DJINJ</u>
Brhd:	Pressure or inches of Hg <u>0 psig</u>	Previous Test Pressure <u>0</u>	Last MIT: <u>07/25/2024</u>
			AnnMTReq: _____

Comment: All injection wells which fail MIT or which are determined to lack mechanical integrity shall be shut in.

Corrective Action: Immediately shut in well and disconnect flowline or disable/LOTO injection pump Date: 02/23/2026

Method of Injection: PUMP FEED

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>ECMC Audit Report Summary On Monday 2/23/2026 at approximately 11:30 hours I, Inspector Tom Peterson, conducted an on-site inspection at the Expedition Water Solutions EWS #6A API #123-47689 in Weld County, Colorado. While there, I observed that the well lacked mechanical integrity. During this inspection the following possible compliance issues were observed: Rule 417.f. with a corrective action date of 2/23/2026. A follow up inspection on this site needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules. This is a summary of the inspection report.</p>	petersont	02/23/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404554814	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7458507
697012489	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7458503