

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/11/2026

Submitted Date:

02/23/2026

Document Number:

701104526

FIELD INSPECTION FORM

Loc ID 324070 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10844
Name of Operator: QB ENERGY OPERATING LLC
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

Findings:

- 7 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Energy, QB		ecmc.inspections@qb-energy.com	QB Inspection mail box

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
89074	WELL	PR	10/09/2008	GW	045-07404	MILLER 11-15 (O11W)	EG

General Comment:

Flowline Integrity Inspection and Tank Integrity Inspection
Methanol and Condensate labels ar in poor condition.
No smoking sign on separator is peeled off.
Install sign to comply with Rule 605.g.(2)
CA Date 03/27/2026
Old unused Fencing material behind tank battery.
Comply with Rule 606
CA Date 03/27/2026
Secondary containment under chemical container is full of fluid.
Maintain secondary containment devices per Rule 912.d.(1).
CA Date 03/06/2026

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Methanol and Condensate labels ar in poor condition. Install sign to comply with Rule 605.g.		
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	No smoking sign on separator is peeled off.		
Corrective Action:	Install sign to comply with Rule 605.g.(2)		Date: 03/27/2026
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:	Fencing material behind tank battery.		
Corrective Action:	Comply with Rule 606		Date: 03/27/2026
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No _____			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:
Flaring:			
Type			

Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 89074 Type: WELL API Number: 045-07404 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Fail	

Comment: Secondary containment under chemical container is full of fluid.

Corrective Action: Maintain secondary containment devices per Rule 912.d.(1).

Date: 03/06/2026

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404554353	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7458217
701104527	Flowline integrity inspection 701104526 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7458214