

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/18/2026

Submitted Date:

02/23/2026

Document Number:

701104530

FIELD INSPECTION FORM

Loc ID 335041 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10844
Name of Operator: QB ENERGY OPERATING LLC
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

Findings:

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Energy, QB		ecmc.inspections@qb-energy.com	QB Inspection mail box
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

General Comment:

Flowline Integrity Inspection and Tank Integrity Inspection
 NW tank is flaking rusted tank around bottom of tank man hatch. Rust is starting on the man hatches of the other tanks.
 NE tank is damage on top of tank at tank thief hatch with a hole in tank seem from tank damage.
 Comply with Rules 608.a.(10)Tank Venting Standards and 608.e Mechanical Conditions.
 CA Date 3/10/2026

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L		Date:

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	300 BBLs	STEEL AST		,
Comment:	NW tank is flaking rusted tank around bottom of tank man hatch. Rust is starting on the man hatches of the other tanks. NE tank is damage on top of tank at tank thief hatch with a hole in tank seem from tank damage.				
Corrective Action:	Comply with Rules 608.a.(10) Tank Venting Standards and 608.e Mechanical Conditions.				Date: 03/10/2026

Paint

Condition:

Other (Content): _____

Other (Capacity): _____

Other (Type): _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
------	--

Comment:		
Corrective Action:		Date:

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404554879	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7458523
701104531	Flowline integrity inspection 701104530 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7458519