

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/23/2026

Submitted Date:

02/23/2026

Document Number:

708908546

FIELD INSPECTION FORM

Loc ID 334774 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
ECMC Operator Number: 10433
Name of Operator: LARAMIE ENERGY LLC
Address: 1700 LINCOLN ST STE 3950
City: DENVER State: CO Zip: 80203

Findings:

- 22 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|-------|---------------------------------------|---------|
| LARAMIE ENERGY | | cogccnotifications@laramie-energy.com | |
| Longworth, Mike | | mike.longworth@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------------|-------------|
| 276680 | WELL | PR | 06/01/2017 | GW | 045-10512 | CASCADE CREEK 797-05-52 | PR |
| 283586 | WELL | PR | 07/12/2006 | GW | 045-11963 | CASCADE CREEK 797-05-45D | PR |
| 283839 | WELL | PR | 06/01/2012 | GW | 045-12011 | CASCADE CREEK 797-5-61D | PR |
| 283842 | WELL | PR | 03/17/2011 | GW | 045-12008 | CASCADE CREEK 797-5-62D | PR |

General Comment:

[This is a Field Inspection/Audit of the scout card, related documents and the location.](#)

Location

| | | | |
|--------------------|-------------|--|-------|
| Lease Road: | | | |
| | Type Access | | |
| comment: | | | |
| Corrective ActionL | | | Date: |

Overall Good:

| | | | |
|----------------------|--|--|-------|
| Signs/Marker: | | | |
| | Type BATTERY | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| | Type CONTAINERS | | |
| Comment: | Chemical tank | | |
| Corrective Action: | | | Date: |
| | Type WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| | Type OTHER | | |
| Comment: | Sign at entrance to location | | |
| Corrective Action: | | | Date: |
| | Type OTHER | | |
| Comment: | Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks. | | |
| Corrective Action: | | | Date: |
| | Type TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| | | | |
|----------------------------------|-----------------------------|--|-------------|
| Emergency Contact Number: | | | |
| | Comment: 911/1-800-891-6191 | | |
| Corrective Action: | | | Date: _____ |

Overall Good:

| | | | |
|--|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No _____ | | | |
| Comment: _____ | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |

| | | | |
|--------------------|---------------------------|--|-----------------|
| Equipment: | | | corrective date |
| Type: Plunger Lift | # 4 | | |
| Comment: | All wells on plunger lift | | |
| Corrective Action: | | | Date: |

| | | | |
|-----------------------------------|---|--|------------------|
| Type: Bird Protectors | # 3 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Gas Meter Run | # 5 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Dehydrator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Bradenhead | # 4 | | |
| Comment: | Taylor plugs located on bradenheads, bradenhead valves are accessible | | |
| Corrective Action: | | | Date: |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Trailer mounted chemical tank | | |
| Corrective Action: | | | Date: |
| Type: Horizontal Heated Separator | # 5 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Other | # 1 | | |
| Comment: | Unused flowline lacks lockout tagout (OOSLAT) | | |
| Corrective Action: | Comply with CECMC Rule 1101 | | Date: 03/02/2026 |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|------------------------------|----------|-----------|---------|--------|
| CONDENSATE | 1 | 300 BBLS | STEEL AST | | , |
| Comment: | Tank equipped with telemetry | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|-------------------------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | | |
| Comment: | Centralized containment | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| METHANOL | 3 | <50 BBLS | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

| | | | | |
|--------------------|-------------------------|---------------------|---------------------|-------------|
| Paint | | | | |
| Condition | Adequate | | | |
| Other (Content) | | | | |
| Other (Capacity) | 500 gal | | | |
| Other (Type) | | | | |
| Berms | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal | Adequate | Walls Sufficent | | |
| Comment: | Centralized containment | | | |
| Corrective Action: | | | | Date: |
| Venting: | | | | |
| Yes/No | NO | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Flaring: | | | | |
| Type | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Inspected Facilities

Facility ID: 276680 Type: WELL API Number: 045-10512 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 283586 Type: WELL API Number: 045-11963 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 283839 Type: WELL API Number: 045-12011 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 283842 Type: WELL API Number: 045-12008 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|----------------------------------|
| Compaction | | | | | | Light compaction in some areas |
| | | Gravel | | | | Sparse to none |
| Check Dams | | | | | | |
| | | | | Material Handling And Spill Prevention | Fail | Failure to maintain chemical BMP |
| Ditches | | | | | | |
| | | Ditches | | | | |
| | | Culverts | | | | |
| Berms | | | | | | |
| | | Rip Rap | | | | |
| | | Check Dams | | | | |
| | | Sediment Traps | | | | |
| | | Compaction | | | | Light compaction in sections |

Comment: 1. Failure to maintain chemical BMP – Chemical tank containment approximately 3/4 full of fluid/BMP not sufficient to contain possible spill

Corrective Action: **Comply with CECMC Rule 1002**

Date: 02/26/2026

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

| Comment | User | Date |
|---|----------|------------|
| <p>CECMC Inspection/Audit Report Summary On 02/23/2026 at approximately 12:25 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection/audit at LARAMIE ENERGY LLC CC 0797-05-52 Pad Location # 334774 in Garfield County Colorado. Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to NSO Habitat area. Location is approximately 250 yards from Conn Creek. While there, I observed normal production operations.</p> <p>During this inspection/audit the following compliance issues were observed:</p> <p>1. Equipment - Unused flowline lacks lockout tagout (OOSLAT) - Comply with Rule 1101 with a CA date of 03/02/2026</p> <p>2. Stormwater - Failure to maintain chemical BMP - Comply with Rule 1002 with a CA date of 02/26/2026</p> <p>A follow up on this site inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules. This is a summary of inspection/audit report.</p> | smelserw | 02/23/2026 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---|---|
| 404555184 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7458814 |
| 708908547 | Inspection/Audit 708908546 Stormwater photo log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7458812 |
| 708908548 | Inspection/Audit 708908546 photo log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7458813 |