

Final Reclamation Inspection

February 6, 2026

Operator: KERR MCGEE OIL & GAS ONSHORE LP

Location ID: 330415

Inspection Document #: 720300095

Weld County, CO

Isaac Thibedeau
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: HSR-KNOX-65N67W 3NWNW

Location ID: 330415




Photo 1. Photo taken from access road looking down on location. Access road has not been reclaimed and remains bare. Due to this there is a high risk stormwater erosion.

Photo 2. Photo taken on access road going to location showing evidence of stormwater rill erosion and bare soil.



Inspection Photos

Location Name: HSR-KNOX-65N67W 3NWNW

Location ID: 330415



Photo 3. Photo taken from location facing north, shows overview of the location. Location does not meet final reclamation standards significant area is bare and large number of weeds are present on location.



Photo 4. Photo taken from location facing east. See comments under photo 3.

Inspection Photos

Location Name: HSR-KNOX-65N67W 3NWNW

Location ID: 330415



Photo 5. Photo taken from southern end of location facing south. Clear line is present where disturbance occurred and vegetation is lacking. Above redline is undisturbed and below was disturbed.



Photo 6. Photo taken from location facing north west, on the north west corner of the well pad. See comment in photo 3.



Inspection Photos

Location Name: HSR-KNOX-65N67W 3NWNW

Location ID: 330415



Photo 7. Photo taken from southeastern edge of location facing west. There is a clear line where well pad was. Where well pad was weeds are present and significant bare areas are present throughout the location.



Photo 8. Photo taken from the south western side of well pad demonstrating a clear outline of where the well pad was and where the road enters.



Inspection Photos

Location Name: HSR-KNOX-65N67W 3NWNW

Location ID: 330415



Photo 9. Photo shows native desirable grass species just off of location on the south eastern side of well head.



Inspection Photos

Location Name: HSR-KNOX-65N67W 3NWNW

Location ID: 330415



Photo 10. Photo shows desirable grass species that was present on location giving some evidence of previous reclamation work however undesirable plants outnumber natives significantly.



Photo 11. Photo shows undesirable plant species russian thistle present on location



Inspection Photos
Location Name: HSR-KNOX-65N67W 3NWNW
Location ID: 330415

Feb 6, 2026 at 10:39:08 AM
+40.432896,-104.885580
10° N
Windsor CO 80550
United States



Photo 12. Photo shows location access road has not been reclaimed, is mostly bare and there is evidence of stormwater erosion (red circle) .

Inspection Photos

Location Name: HSR-KNOX-65N67W 3NWNW

Location ID: 330415



Photo 13. Photo shows erosion on main access road.



Photo 14. Photo shows erosion on main access road.



Inspection Photos
Location Name: HSR-KNOX-65N67W 3NWNW
Location ID: 330415



Photo 15. Photo shows erosion on main access road.



Photo 16. Photo shows soil from main access road filling cattle guard at the access gate to SH 257.

