

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/02/2026

Submitted Date:

03/02/2026

Document Number:

719001479

FIELD INSPECTION FORM

Loc ID: 333079 Inspector Name: GARCIA, CHARLES On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10464
Name of Operator: CATAMOUNT ENERGY PARTNERS LLC
Address: 600 17TH STREET STE 1400S
City: DENVER State: CO Zip: 80202

Findings:

- 15 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, General		Inspections@catamountep.com	SJB inspections
McDonough, Corey		corey.mcdonough@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205173	WELL	PR	01/12/2024	GW	007-06049	ARGENTA FEE 18	PR
205217	WELL	PR	04/01/2020	CBM	007-06094	Argenta Fee 19	PR

General Comment:

Inspection Report Summary
On 2/26/26 | Inspector Charles Garcia conducted an on-site inspection.
Location: ARGENTA FEE 19, ARGENTA FEE 18
API# 067-06049
API# 067-06094
Operator: CATAMOUNT ENERGY PARTNERS LLC
County: LaPlata
All prior CA's still stand.

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	LOCATION SIGNS ARGENTA FEE 18 SHOWS BIG RUN PRODUCTION NOT CATAMOUNT		
Corrective Action:	Install sign or correct sign per rule 605		Date: 03/09/2026
Emergency Contact Number:			
Comment:	903-521-2990 911 EMERGENCY		
Corrective Action:			Date:
Good Housekeeping:			
Type	STORAGE OF SUPL		
Comment:	Land owner has Equipment on location. SEE LOCATION PICTURES		
Corrective Action:	Equipment not necessary for oil and gas operations.Store equipment off pad/interim reclamation area or obtain variance per rule 606.a(2),		Date: 03/02/2026
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment: <input style="width: 100%;" type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	CATTLE PANELS		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	HOG WIRE		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	CATTLE PANELS		
Corrective Action:			Date:
Type	OTHER		
Comment:	METER HOUSES TELEMETRY EQUIPMENT HOG WIRE		
Corrective Action:			Date:
Equipment:			
Type: Bird Protectors	# 2	corrective date	
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 2		

Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:			Date:
Type: Flow Line	# 2		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Other	# 2		
Comment:	WELLHEADS		
Corrective Action:			Date:
Type: Other	# 2		
Comment:	METER HOUSES CALIBRATION IN COMPLIANCE		
Corrective Action:			Date:
Type: Bradenhead	# 2		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	GAS		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	At Argenta 18 well, pump jack and prime mover appear unused and non-serviceable. Remove all unused and non-serviceable equipment or maintain and return to service		
Corrective Action:	Remove all unused and non-serviceable equipment or maintain and return to service per 1000 series rules		Date: 05/01/2026

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 205173 Type: WELL API Number: 007-06049 Status: PR Insp. Status: PR

Producing Well

Comment: SHARED LOCATION WITH ARGENTA FEE 18

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 10/28/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 205217 Type: WELL API Number: 007-06094 Status: PR Insp. Status: PR

Producing Well

Comment: _____

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 10/28/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719001480	LOCATION PICTURES	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7465895